

#### **Check MOT history**

This is a new service – <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX?</u> vrm=T27RKA&make result=MERCEDES-

BENZ&model result=VITO+113+CDI+TRAVELINER&mot first used date=2013-03-

21&vehicle age=4033&mot\_expiry\_date=2025-04-

28&mot\_expiry\_date\_days\_left=388&user\_satisfaction\_banner=0&vehicle\_data\_origin=MTS&vehicle\_type=LGV) to help us improve.

< Back

## T27 RKA

# MERCEDES-BENZ VITO 113 CDI TRAVELINER

Check another vehicle (/)

Colour Fuel type Date registered
Silver Diesel 21 March 2013

MOT valid until

# 28 April 2025

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

<u>Download test certificates (/enter-document-reference?registration=T27RKA)</u>

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes)</u>.

Hide all sections

## **MOT** history

Check mileage recorded at test, expiry date, and test outcome

Hide

Date tested 4 April 2024

**PASS** 

Mileage 356,487 miles

Test location

View test location

MOT test number 9116 8863 6031

Expiry date 28 April 2025

Date tested 13 April 2023

**PASS** 

Mileage 309,266 miles

MOT test number **9027 1540 3243** 

Test location

Expiry date 28 April 2024

View test location

Repair as soon as possible (minor defects):

• Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Monitor and repair if necessary (advisories):

- Side repeater slightly discoloured both faded (4.4.3 (a))
- Rear Exhaust mounting defective one mount broken (6.1.2 (a))
- Front Exhaust mounting defective one mounting broken (6.1.2 (a))
- · brake pad warning light on but no obvious faults
- · knocking noise n/s/f but no obvious faults
- ▶ What are advisories?

Date tested 29 April 2022

**PASS** 

Mileage 271,219 miles

MOT test number **2531 0103 9798** 

Test location

Expiry date 28 April 2023

View test location

Monitor and repair if necessary (advisories):

- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- What are advisories?

Date tested 27 April 2022



Mileage 271,204 miles

MOT test number **6310 5886 8755** 

Test location

View test location

Repair immediately (major defects):

 Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Monitor and repair if necessary (advisories):

- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ▶ What are defects and advisories?

Date tested 28 April 2021

**PASS** 

Mileage 223,930 miles

Test location

View test location

MOT test number **9126 0653 3324** 

Expiry date **27 April 2022** 

Date tested 20 April 2021

**FAIL** 

Mileage 222,478 miles

MOT test number **3883 8331 5978** 

Test location

View test location

Repair immediately (major defects):

- Nearside Front Service brake excessively binding (1.2.1 (f))
- Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Nearside Headlamp aim not tested (4.1.2 (b))
- Nearside Front Body component damaged and likely to cause injury (6.2.1 (a) (i))
- Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Parking brake efficiency below requirements (1.4.2 (a) (i))
- What are defects?

Date tested 28 April 2020

**PASS** 

Mileage 192,520 miles MOT test number **8612 0295 8425** 

Test location

Expiry date 27 April 2021

View test location

Repair as soon as possible (minor defects):

 Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Monitor and repair if necessary (advisories):

- Brake pedal wearing smooth and small split in rubber (1.1.2 (c))
- · Rear exhaust joining clamp missing
- ▶ What are advisories?

Date tested **24 April 2020** 

Mileage 192,950 miles MOT test number **2650 5228 6280** 



Test location

View test location

Repair immediately (major defects):

- Fuel system component leaking (6.1.3 (b) (i))
- Offside Rear Service brake excessively binding (1.2.1 (f))

Repair as soon as possible (minor defects):

 Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Monitor and repair if necessary (advisories):

- Brake pedal wearing smooth and small split in rubber (1.1.2 (c))
- Offside Front Day running light not working
- · Rear exhaust joining clamp missing
- ► What are defects and advisories?

Date tested 19 March 2020

**FAIL** 

Mileage 192,309 miles MOT test number **1825 4967 5247** 

Test location

View test location

Repair immediately (major defects):

- Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Offside Rear Parking brake lever defective so that it cannot be satisfactorily operated not releasing. Binding (1.1.6 (d))

Monitor and repair if necessary (advisories):

- OSF DRL inop
- What are defects and advisories?

Date tested

14 March 2019

**PASS** 

Mileage 146,636 miles

MOT test number **8413 8392 0877** 

Test location

Expiry date 20 March 2020

View test location

#### The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested **22 February 2018** 

**PASS** 

Mileage 90,623 miles

Test location

View test location

MOT test number **2240 1597 0628** 

Expiry date 20 March 2019

Date tested **27 February 2017** 

**PASS** 

Mileage 63,497 miles

Test location

► View test location

MOT test number **2708 0833 2186** 

Expiry date 20 March 2018

Date tested 17 March 2016

**PASS** 

Mileage 40,753 miles

Test location

View test location

MOT test number **8144 9336 6819** 

Expiry date **20 March 2017** 

#### Check for vehicle recalls

See if MERCEDES-BENZ VITO 113 CDI TRAVELINER T27RKA has outstanding recalls





This vehicle has an outstanding recall.

If you're the owner or driver of this vehicle, contact the local MERCEDES-BENZ dealership to arrange a free repair.

If the recalled component has been repaired recently, it can take several weeks for the manufacturer to update their records.

This information is provided by the vehicle manufacturer. If you think the recall information is wrong, contact your local MERCEDES-BENZ dealership.

<u>Cookies Terms and conditions Privacy notice Accessibility statement MOT history API Service status</u>

Built by the **Driver & Vehicle Standards Agency** 

#### **OGL**

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

© Crown copyright