



Check MOT history (<https://www.gov.uk/check-mot-history>)

FD08AWH

## VAUXHALL VIVARO

Colour

**Silver**

Fuel type

**Diesel**

Date registered

**20 May 2008**

MOT valid until

**6 October 2019**

### MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories

Date tested

**2 October 2018**

Mileage

**280,329 miles**

MOT test number

**2002 6995 7622**

**PASS**

Test location

Expiry date

**6 October 2019**

### The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested

**28 September 2017**

Mileage

**260,620 miles**

MOT test number

**9700 4328 7736**

**PASS**

Test location

Expiry date

**6 October 2018**

Advisory notice item(s)

- Oil leak
- Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Wipers deteriorated

- NSR tyre wearing on edge
- Nail in OSR tyre on the inner edge

Date tested  
**30 September 2016**

**PASS**

Mileage  
**238,406 miles**

MOT test number  
**4371 3809 3743**

Test location

Expiry date  
**6 October 2017**

Advisory notice item(s)

- **Nearside Front Shock absorber has a light misting of oil (2.7.3)**

Date tested  
**29 September 2016**

**FAIL**

Mileage  
**238,402 miles**

MOT test number  
**7663 8871 8479**

Test location

Reason(s) for failure

- **Nearside Front Front position lamp(s) not working (1.1.A.3b)**
- **Registration plate lamp not working (1.1.C.1d)**
- **Nearside Front Headlamp aim too low (1.8)**
- **Offside Front Headlamp aim too low (1.8)**
- **Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**
- **Nearside Front Anti-roll bar linkage has excessive play in a pin/bush drop link (2.4.G.2)**
- **Offside Front Anti-roll bar linkage has excessive play in a pin/bush drop link (2.4.G.2)**
- **Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**  
Dangerous
- **Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**
- **Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**
- **Nearside Front Sub-frame rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**

- **Offside Front Sub-frame rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**

Advisory notice item(s)

- **Nearside Front Shock absorber has a light misting of oil (2.7.3)**

Date tested  
**6 October 2015**

**PASS**

Mileage  
**216,250 miles**

Test location

MOT test number  
**8599 3440 7296**

Expiry date  
**6 October 2016**

Advisory notice item(s)

- **Offside Outer Seat belt damaged but webbing not significantly weakened centre row of seats (5.2.2a)**
- **Nearside Front Tyre worn close to the legal limit 205/65r16c (4.1.E.1)**

Date tested  
**29 September 2015**

**FAIL**

Mileage  
**215,764 miles**

Test location

MOT test number  
**6004 6493 4031**

Reason(s) for failure

- **Nearside Outer Seat belt damaged sufficient to significantly weakened the webbing centre row of seats (5.2.2a)**
- **Nearside Track rod end ball joint has excessive play (2.2.B.1f)**
- **Nearside Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**
- **Offside Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**

Advisory notice item(s)

- **Offside Outer Seat belt damaged but webbing not significantly weakened centre row of seats (5.2.2a)**

- **Nearside Front Tyre worn close to the legal limit 205/65r16c (4.1.E.1)**

Date tested  
**1 October 2014**

**PASS**

Mileage  
**186,834 miles**

MOT test number  
**1899 7497 4226**

Test location

Expiry date  
**6 October 2015**

Advisory notice item(s)

- **Nearside Outer Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**
- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**
- **advise : nearside door mirror glass missing, other obligatory mirrors present.**
- **Oil leak**
- **advise : no diesel smoke level recorded.**

Date tested  
**1 October 2014**

**FAIL**

Mileage  
**186,834 miles**

MOT test number  
**9063 9497 4287**

Test location

Reason(s) for failure

- **Offside Stop lamp not working (1.2.1b)**
- **Nearside Front position lamp(s) not working (1.1.A.3b)**

Advisory notice item(s)

- **Nearside Outer Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**
- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**
- **advise : nearside door mirror glass missing, other obligatory mirrors present.**
- **Oil leak**
- **advise : no diesel smoke level recorded.**

Date tested  
**5 October 2013**

**PASS**

Mileage  
**149,681 miles**

MOT test number  
**5263 9837 3273**

Test location

Expiry date

6 October 2014

Advisory notice item(s)

- **Front Brake pad(s) wearing thin (3.5.1g)**
- **Offside Outer Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**
- **Nearside Outer Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**
- **advise : area around fuel sender cap / seal damp.**
- **Engine covers fitted obscuring some components in the engine bay**

Date tested  
**5 October 2013**

Mileage  
**149,679 miles**

MOT test number  
**6453 8857 3276**

**FAIL**

Test location

Reason(s) for failure

- **Offside Track rod end ball joint has excessive play (2.2.B.1f)**
- **Offside Steering rack insecure (2.2.B.1a)**
- **Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**

Date tested  
**28 September 2012**

Mileage  
**89,170 miles**

MOT test number  
**5754 9227 2212**

**PASS**

Test location

Expiry date  
**6 October 2013**

Advisory notice item(s)

- **Play in steering rack inner joint(s)**

Date tested  
**27 September 2012**

Mileage  
**88,764 miles**

MOT test number  
**8076 4187 2227**

**FAIL**

Test location

Reason(s) for failure

- **Nearside Front position lamp(s) not working (1.1.A.3b)**

- Offside Front position lamp(s) not working (1.1.A.3b)
- Offside Headlamp not working on dipped beam (1.7.5a)
- Registration plate lamp not working (1.1.C.1d)
- Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Brakes imbalanced across an axle (3.7.B.5b)

Date tested  
7 October 2011

**PASS**

Mileage  
58,887 miles

Test location

MOT test number  
1887 8098 1288

Expiry date  
6 October 2012

Advisory notice item(s)

- there is slight play in the steering rack, but it is not considered excessive

Date tested  
5 October 2011

**FAIL**

Mileage  
58,742 miles

Test location

MOT test number  
8897 1867 1223

Reason(s) for failure

- Registration plate lamp not working (1.1.C.1d)
- Offside Inner Track rod end ball joint has excessive play (2.2.B.1f)
- Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Date tested  
5 October 2010

**PASS**

Mileage  
35,074 miles

Test location

MOT test number  
3746 7827 0235

Expiry date  
6 October 2011

Advisory notice item(s)

- rear brake discs slightly worn

Date tested

Mileage

MOT test number

5 October 2010

35,074 miles

4204 9817 0212

**FAIL**

Test location

Reason(s) for failure

- **Offside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)**
- **Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**
- **Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**

Advisory notice item(s)

- **rear brake discs slightly worn**

Date tested

7 October 2009

**PASS**

Mileage

12,775 miles

Test location

MOT test number

6138 1018 9230

Expiry date

6 October 2010

Advisory notice item(s)

- **Cuts in N/S/F tyre wall**

**Outstanding vehicle recalls**

Check if VAUXHALL VIVARO FD08AWH has outstanding recalls

