



Check MOT history (<https://www.gov.uk/check-mot-history>)

This vehicle's MOT has expired

You can be fined up to £1000 for driving without a valid MOT
This vehicle may be MOT exempt, for more information refer to

DE09HHG

SKODA OCTAVIA

Colour	Fuel type	Date registered
Blue	Diesel	27 April 2009

MOT expired on
18 August 2019

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested	Mileage	MOT test number
21 August 2019	214,836 miles	8702 6096 7195

FAIL

Test location

Repair immediately (major defects):

- **Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**
- **Nearside Rear Position lamp not working (4.2.1 (a) (ii))**
- **Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**

Repair as soon as possible (minor defects):

- **Offside Rear Tyre obviously under inflated (5.2.3 (l))**

- **Offside Rear Lower Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Inner Perished (5.3.4 (a) (i))**
- **Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Inner Perished (5.3.4 (a) (i))**
- **Nearside Rear Light cluster damaged**

Date tested
7 August 2018

PASS

Mileage
204,992 miles

MOT test number
5249 5590 2052

Test location

Expiry date
18 August 2019

Monitor and repair if necessary (advisories):

- **Nearside Rear Shock absorbers has slight external damage to the casing cover loose (5.3.2 (b))**
- **Offside Rear Shock absorbers has slight external damage to the casing cover loose (5.3.2 (b))**
- **Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**

Date tested
7 August 2018

FAIL

Mileage
204,992 miles

MOT test number
1638 4233 1993

Test location

Repair immediately (major defects):

- **Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Shock absorbers has slight external damage to the casing cover loose (5.3.2 (b))**
- **Offside Rear Shock absorbers has slight external damage to the casing cover loose (5.3.2 (b))**
- **Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
10 August 2017

PASS

Mileage
195,799 miles

Test location

MOT test number
9372 5603 7884

Expiry date
18 August 2018

Advisory notice item(s)

- **Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Nearside Rear Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement smaller arm (2.4.G.2)**
- **Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**
- **Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush both sides (2.4.G.2)**

Date tested
9 August 2017

FAIL

Mileage
195,785 miles

Test location

MOT test number
6878 4781 9110

Reason(s) for failure

- **Front Shock absorber has a serious fluid leak both sides (2.7.3)**

Advisory notice item(s)

- **Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Nearside Rear Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement smaller arm (2.4.G.2)**
- **Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**
- **Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush both sides (2.4.G.2)**

Date tested
19 August 2016

PASS

Mileage
189,878 miles

MOT test number
5595 5601 8864

Test location

Expiry date
18 August 2017

Advisory notice item(s)

- **Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**
- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**
- **Offside Front Tyre worn close to the legal limit (4.1.E.1)**

Date tested
11 August 2015

PASS

Mileage
170,715 miles

MOT test number
4968 7081 5750

Test location

Expiry date
10 August 2016

Advisory notice item(s)

- **under covers fitted**
- **engine covers fitted**
- **Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**

Date tested
10 August 2015

FAIL

Mileage
170,712 miles

Test location

MOT test number
9795 5245 2758

Reason(s) for failure

- **Offside Side repeater not working (1.4.A.2c)**
- **Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**
- **Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**

Advisory notice item(s)

- **under covers fitted**
- **engine covers fitted**

Date tested
28 August 2014

PASS

Mileage
148,133 miles

Test location

MOT test number
4871 8094 4258

Expiry date
23 September 2015

Date tested
26 August 2014

FAIL

Mileage
148,133 miles

Test location

MOT test number
4370 7823 4291

Reason(s) for failure

- **Supplementary Restraint System warning lamp indicates a fault (5.4.2)**

Date tested
24 September 2013

PASS

Mileage
125,920 miles

Test location

MOT test number
5482 0776 3268

Expiry date
23 September 2014

Date tested
24 September 2013

FAIL

Mileage
125,920 miles

Test location

MOT test number
3855 8766 3258

Reason(s) for failure

- **Nearside Headlamp aim too high (1.8)**

Date tested
20 April 2012

PASS

Mileage
97,411 miles

Test location

MOT test number
2071 9161 2126

Expiry date
27 April 2013

Outstanding vehicle recalls

Check if SKODA OCTAVIA DE09HHG has outstanding recalls
