

Check MOT history (<https://www.gov.uk/check-mot-history>)

SB61RXZ

# MERCEDES-BENZ VITO

Colour  
**Silver**

Fuel type  
**Diesel**

Date registered  
**21 February 2012**

MOT valid until  
**19 February 2023**

## MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested  
**15 February 2022**

**PASS**

Mileage  
**283,426 miles**

Test location

MOT test number  
**8114 6669 2324**

Expiry date  
**19 February 2023**

Repair as soon as possible (minor defects):

- **Nearside Windscreen wiper blade defective (3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**

Date tested  
**12 February 2021**

**PASS**

Mileage  
**267,198 miles**

Test location

MOT test number  
**2374 0583 9849**

Expiry date  
**19 February 2022**

Monitor and repair if necessary (advisories):

- **Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bushes both sides (5.3.4 (a) (i))**

Date tested  
**8 February 2021**

**FAIL**

Mileage  
**267,190 miles**

MOT test number  
**4555 8015 5590**

Test location

Do not drive until repaired (dangerous defects):

- **Rear Coil spring mounting insecure to the extent that relative movement is visible both sides bump stops missing and springs come out (5.3.1 (a) (ii))**

Repair immediately (major defects):

- **Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**
- **Nearside Front Seat belt not functioning as intended (7.1.2 (c))**
- **Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**
- **Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**

Repair as soon as possible (minor defects):

- **Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt twisted badly (2.1.3 (g) (i))**

Monitor and repair if necessary (advisories):

- **Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**
- **Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement drop link both sides (5.3.4 (a) (i))**
- **Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bushes both sides (5.3.4 (a) (i))**

Date tested  
**20 February 2020**

**PASS**

Mileage  
**256,150 miles**

MOT test number  
**8945 2404 8491**

Test location

Expiry date  
**19 February 2021**

Date tested

Mileage

MOT test number

19 February 2020

256,140 miles

1654 2003 7321

**FAIL**

Test location

Do not drive until repaired (dangerous defects):

- **Tyre tread depth below requirements of 1.6mm all 4 below 1.6 front have wire and cord exposed rears split and damaged (5.2.3 (e))**

Repair immediately (major defects):

- **Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **parking break only just met requirements**

---

Date tested

**30 January 2019**

Mileage

**242,685 miles**

MOT test number

**9361 4502 5528**

**PASS**

Test location

Expiry date

**17 February 2020**

---

### The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

---

Date tested

**3 February 2018**

Mileage

**221,363 miles**

MOT test number

**9966 0851 3975**

**PASS**

Test location

Expiry date

**17 February 2019**

---

Date tested

**31 January 2018**

Mileage

**221,363 miles**

MOT test number

**5271 2247 7391**

**FAIL**

Test location

Reason(s) for failure

- **front brake application uneven (3.7.B.2)**
- **Offside front brake binding (3.7.B.1)**
- **Offside Steering rack gaiter split (2.2.D.2d)**

---

Date tested

**18 January 2017**

Mileage

**173,416 miles**

MOT test number

**6493 7679 2498**

# PASS

Test location

Expiry date

**17 February 2018**

Date tested

**10 February 2016**

# PASS

Mileage

**118,803 miles**

MOT test number

**9865 4628 6114**

Test location

Expiry date

**17 February 2017**

Date tested

**18 February 2015**

# PASS

Mileage

**93,039 miles**

MOT test number

**4770 4964 5051**

Test location

Expiry date

**17 February 2016**

Advisory notice item(s)

- **Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Offside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Parking brake lever has little reserve travel (3.1.6b)**
- **Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**
- **Nail in nearside front tyre**

Date tested

**14 February 2014**

# PASS

Mileage

**62,748 miles**

MOT test number

**4451 4594 4024**

Test location

Expiry date

**17 February 2015**

Advisory notice item(s)

- **Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**
- **Parking brake lever has little reserve travel (3.1.6b)**
- **slight slit brake pedal rubber/both rear tyres worn inner edges**

Date tested

**18 February 2013**

Mileage

**32,082 miles**

MOT test number

**8750 9954 3008**

## Outstanding vehicle recalls

Check if MERCEDES-BENZ VITO SB61RXZ has outstanding recalls

---