

## **Check MOT history**

This is a new service – <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX?</u> <u>vrm=FY61XHR&make\_result=SKODA&model\_result=OCTAVIA&mot\_first\_used\_date=2011-11-</u> <u>30&vehicle\_age=4129&mot\_expiry\_date=2023-10-</u> <u>03&mot\_expiry\_date\_days\_left=196&user\_satisfaction\_banner=0&vehicle\_data\_origin=MTS&vehicle\_ty</u> to help us improve.

< <u>Back</u>

# FY6I XHR SKODA OCTAVIA

Check another vehicle (/)

Colour Grey

### Fuel type **Diesel**

Date registered 30 November 2011 MOT valid until 2 Octobor 2022

**3 October 2023** 

<u>Get an MOT reminder (https://www.gov.uk/mot-reminder)</u> by email or text.

Download test certificates (/enter-v5c?registration=FY61XHR)

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA</u> (<u>https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes</u>).

Show all sections

## **MOT** history

Check mileage recorded at test, expiry date, and test outcome

• Hide

Date tested 4 October 2022

PASS

Mileage 294,262 miles

Test location

View test location

MOT test number 7190 9674 5457

Expiry date 3 October 2023

Monitor and repair if necessary (advisories):

• Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

What are advisories?

Date tested 6 September 2021



## Mileage 268,057 miles

**Test location** 

View test location

MOT test number 5892 3357 5203

Expiry date **30 September 2022** 

Repair as soon as possible (minor defects):

- Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

- Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

What are advisories?

Date tested 6 September 2021

FAIL

Mileage 268,022 miles

**Test location** 

View test location

MOT test number 8909 1438 4420

Repair immediately (major defects):

- Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

• Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Repair as soon as possible (minor defects):

- Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

What are defects and advisories?

Date tested 15 September 2020



## Mileage 250,930 miles

**Test location** 

View test location

MOT test number **7268 0436 5151** 

Expiry date **30 September 2021** 

Monitor and repair if necessary (advisories):

- Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- What are advisories?

Date tested 28 March 2019



Mileage 220,477 miles

**Test location** 

View test location

MOT test number 6917 1313 8252

Expiry date **30 September 2020** 

Monitor and repair if necessary (advisories):

- Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm and wearing on inner edge (5.2.3 (e))
- What are advisories?

Date tested 27 March 2019

FAIL

Mileage 220,457 miles

**Test location** 

#### View test location

MOT test number

#### 1523 0277 5190

Repair immediately (major defects):

 Offside Front Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))

Monitor and repair if necessary (advisories):

- Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm and wearing on inner edge (5.2.3 (e))
- What are defects and advisories?

#### The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested 29 March 2018



## Mileage 193,060 miles

**Test location** 

View test location

MOT test number 4227 7041 7516

Expiry date 31 March 2019

Advisory notice item(s)

- Offside Front Front wheel bearing has slight play (2.5.A.3c)
- Offside Front Side indicator only 33% working
- What are advisories?

Date tested **30 March 2017** 



#### Mileage 164,380 miles

**Test location** 

View test location

MOT test number 6366 5360 2843

Expiry date 31 March 2018

Date tested **1 April 2016** 



Mileage 129,269 miles

Test location

View test location
MOT test number
8217 0117 7206

Expiry date 31 March 2017

Date tested 1 April 2016

FAIL

Mileage 129,267 miles

Test location

View test location

MOT test number 1472 5366 0743

Reason(s) for failure

• Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



#### Date tested 18 November 2015



Mileage 117,742 miles

**Test location** 

View test location

MOT test number 5353 3194 7967

Expiry date 30 November 2016

Advisory notice item(s)

- Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Offside Front Shock absorber has a light misting of oil (2.7.3)

#### Date tested 12 November 2014



Mileage 94,777 miles

Test location

View test location

MOT test number 5552 6641 4312

Reason(s) for failure

- Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- What are failures?

Date tested

#### 12 November 2014



Mileage 94,777 miles

Test location

View test location

MOT test number 5591 2641 4362

Expiry date **30 November 2015** 

### **Check for vehicle recalls**

See if SKODA OCTAVIA FY61XHR has outstanding recalls

Show

<u>Cookies</u> <u>Terms and conditions</u> <u>Privacy notice</u> <u>Accessibility statement</u> <u>MOT history API</u> <u>Service status</u>

Built by the Driver & Vehicle Standards Agency

### OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

© Crown copyright