GOV.UK

Check MOT history

This is a new service — <u>Complete a quick survey (https://www.smvrm=TD11CAB&make_result=CITROEN&model_result=BERLINGO&n27&vehicle_age=3842&mot_expiry_date=2023-10-03&mot_expiry_date_days_left=181&user_satisfaction_banner=0&vehto help us improve.</u>

< Back

TDII CAB

CITROEN BERLINGO

Check another vehicle (/)

Colour

Blue

Fuel type

Diesel

Date registered

27 September 2012

MOT valid until

3 October 2023

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-v5c?registration=TD11CAB)

If you think the MOT expiry date or any of the vehicle details are wrong: contact_DVSA (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).



MOT history

Check mileage recorded at test, expiry date, and test outcome



Date tested **30 September 2022**



Mileage 127,604 miles

Test location

View test location

MOT test number 9306 3411 4584

Expiry date

3 October 2023

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- What are advisories?

Date tested

1 October 2021



Mileage

97,823 miles

Test location

View test location

MOT test number

7925 7240 7649

Expiry date

3 October 2022

- o/s/r brake binding slightly
- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

- Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- What are advisories?

Date tested

30 September 2021



Mileage

97,819 miles

Test location

View test location

MOT test number

6076 1854 2827

Repair immediately (major defects):

 Nearside Front Upper Macpherson strut mounting damaged and seriously weakened (5.3.3 (b) (i))

Repair as soon as possible (minor defects):

 Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

- o/s/r brake binding slightly
- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

- Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- What are defects and advisories?

Date tested

17 September 2020



Mileage

75,296 miles

Test location

View test location

MOT test number

2313 7478 4221

Expiry date

3 October 2021

Monitor and repair if necessary (advisories):

- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- What are advisories?

Date tested

15 September 2020



Mileage

75,268 miles

Test location

View test location

MOT test number

1828 3962 0591

Repair immediately (major defects):

- Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Monitor and repair if necessary (advisories):

- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ▶ What are defects and advisories?

Date tested

4 October 2019



Mileage 49,138 miles

Test location

View test location

MOT test number 6578 9809 1492

Expiry date

3 October 2020

Monitor and repair if necessary (advisories):

- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- interior trim has movement when handbrake is operated
- What are advisories?

Date tested

4 October 2019



Mileage

49,138 miles

Test location

View test location

MOT test number

8480 7097 4481

Repair immediately (major defects):

 Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))

- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- interior trim has movement when handbrake is operated