

Check MOT history

This is a new service – [Complete a quick survey](https://www.smvrm=SV13JKZ&make_result=MERCEDES-BENZ&model_result=VITO+113+CDI+TRAVELINER&mot_first_used_21&vehicle_age=3674&mot_expiry_date=2023-04-28&mot_expiry_date_days_left=16&user_satisfaction_banner=0&vehic) (https://www.smvrm=SV13JKZ&make_result=MERCEDES-BENZ&model_result=VITO+113+CDI+TRAVELINER&mot_first_used_21&vehicle_age=3674&mot_expiry_date=2023-04-28&mot_expiry_date_days_left=16&user_satisfaction_banner=0&vehic) to help us improve.

[< Back](#)

**This vehicle's MOT
expires soon**

SVI3 JKZ

**MERCEDES-BENZ VITO
113 CDI TRAVELINER**

[Check another vehicle \(/\)](#)

Colour

Silver

Fuel type

Diesel

Date registered

21 March 2013

MOT valid until

28 April 2023

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-v5c?registration=SV13JKZ\)](/enter-v5c?registration=SV13JKZ)

If you think the MOT expiry date or any of the vehicle details are wrong: [contact DVSA \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).

 [Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

 [Hide](#)

Date tested

29 April 2022

PASS

Mileage

271,219 miles

Test location

 [View test location](#)

MOT test number
2531 0103 9798

Expiry date
28 April 2023

Monitor and repair if necessary (advisories):

- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested
27 April 2022

FAIL

Mileage
271,204 miles

Test location

▶ [View test location](#)

MOT test number
6310 5886 8755

Repair immediately (major defects):

- **Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**

Monitor and repair if necessary (advisories):

- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are defects and advisories?](#)

Date tested

28 April 2021

PASS

Mileage

223,930 miles

Test location

▶ [View test location](#)

MOT test number

9126 0653 3324

Expiry date

27 April 2022

Date tested

20 April 2021

FAIL

Mileage

222,478 miles

Test location

▶ [View test location](#)

MOT test number

3883 8331 5978

Repair immediately (major defects):

- **Nearside Front Service brake excessively binding (1.2.1 (f))**
- **Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**
- **Nearside Headlamp aim not tested (4.1.2 (b))**

- **Nearside Front Body component damaged and likely to cause injury (6.2.1 (a) (i))**
- **Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**
- **Parking brake efficiency below requirements (1.4.2 (a) (i))**

▶ [What are defects?](#)

Date tested

28 April 2020

PASS

Mileage

192,520 miles

Test location

▶ [View test location](#)

MOT test number

8612 0295 8425

Expiry date

27 April 2021

Repair as soon as possible (minor defects):

- **Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Brake pedal wearing smooth and small split in rubber (1.1.2 (c))**
- **Rear exhaust joining clamp missing**

▶ [What are advisories?](#)

Date tested
24 April 2020

FAIL

Mileage
192,950 miles

Test location

▶ [View test location](#)

MOT test number
2650 5228 6280

Repair immediately (major defects):

- **Fuel system component leaking (6.1.3 (b) (i))**
- **Offside Rear Service brake excessively binding (1.2.1 (f))**

Repair as soon as possible (minor defects):

- **Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Brake pedal wearing smooth and small split in rubber (1.1.2 (c))**
- **Offside Front Day running light not working**
- **Rear exhaust joining clamp missing**

▶ [What are defects and advisories?](#)

Date tested
19 March 2020

FAIL

Mileage

192,309 miles

Test location

▶ [View test location](#)

MOT test number

1825 4967 5247

Repair immediately (major defects):

- **Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**
- **Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**
- **Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Offside Rear Parking brake lever defective so that it cannot be satisfactorily operated not releasing. Binding (1.1.6 (d))**

Monitor and repair if necessary (advisories):

- **OSF DRL inop**

▶ [What are defects and advisories?](#)

Date tested

14 March 2019

PASS

Mileage

146,636 miles

Test location

▶ [View test location](#)

MOT test number
8413 8392 0877

Expiry date
20 March 2020

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more](https://www.gov.uk/government/news/mot-changes-20-may-2018) (<https://www.gov.uk/government/news/mot-changes-20-may-2018>).

Date tested
22 February 2018

PASS

Mileage
90,623 miles

Test location

▶ [View test location](#)

MOT test number
2240 1597 0628

Expiry date
20 March 2019

Date tested
27 February 2017

PASS

Mileage

63,497 miles

Test location

▶ [View test location](#)

MOT test number

2708 0833 2186

Expiry date

20 March 2018

Date tested

17 March 2016

PASS

Mileage

40,753 miles

Test location

▶ [View test location](#)

MOT test number

8144 9336 6819

Expiry date

20 March 2017

Check for vehicle recalls

See if MERCEDES-BENZ VITO 113 CDI TRAVELINER SV13JKZ has outstanding recalls

 [Show](#)

[Cookies](#) [Terms and conditions](#)

[Privacy notice](#)

[Accessibility statement](#)

[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#).

OGI

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)