GOV.UK Geck MOT history

This is a new service – <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX?</u> <u>vrm=EY55OUD&make_result=VOLKSWAGEN&model_result=SHARAN&mot_first_used_date=2005-09-</u> <u>01&vehicle_age=6747&mot_expiry_date=2025-01-</u> <u>08&mot_expiry_date_days_left=322&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV</u>) to help us improve.

< <u>Back</u>

We need your help

Help us improve this service. <u>Complete a quick</u> <u>survey.</u>

EY55 OUD VOLKSWAGEN SHARAN

Check another vehicle (/)

Colour Black Fuel type **Diesel**

Date registered **1 September 2005**

MOT valid until 8 January 2025

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-document-reference?registration=EY55OUD)

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA</u> (<u>https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes</u>).

 \odot Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

Date tested 9 January 2024

Mileage 252,794 miles

MOT test number 8928 8934 4254



Test location

View test location

Expiry date 8 January 2025

Date tested 9 January 2023 PASS

Mileage 229,284 miles

Test location

View test location

MOT test number 7212 2893 5872

Expiry date 8 January 2024

Monitor and repair if necessary (advisories):

- Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- What are advisories?

Date tested 5 January 2023

FAIL

Mileage 229,076 miles

MOT test number 3892 8852 8472

Test location

View test location

Repair immediately (major defects):

- Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Monitor and repair if necessary (advisories):

- Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- What are defects and advisories?

Date tested
13 December 2021

PASS

207,575 miles

MOT test number 8023 6545 9943

Test location

Mileage

Expiry date


View test location
7 January 2023

Repair as soon as possible (minor defects):

• Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- What are advisories?



The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find</u> <u>out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested 5 July 2017	Mileage 94,571 miles	MOT test number 7976 7775 8274
PASS	Test location	Expiry date 7 July 2018
	View test location	
Date tested 6 July 2016	Mileage 81,974 miles	MOT test number 4962 9545 3816
PASS	Test location	Expiry date
	View test location	7 July 2017
Date tested 3 July 2015	Mileage 72,496 miles	MOT test number 7472 1478 5117
PASS	Test location	Expiry date
	View test location	7 July 2016
Date tested 8 July 2014	Mileage 61,555 miles	MOT test number 2398 4928 4108
PASS	Test location	Expiry date
	View test location	7 July 2015
	Advisory notice item(s) Nearside Front Tyre worn close to the legal limit (4.1.E.1) Offside Front Tyre worn close to the legal limit (4.1.E.1) 	
	 Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2) 	
	What are advisories?	

Date tested 7 July 2014 Mileage 61,555 miles

5759 2898 4135

MOT test number

Test location

View test location


Reason(s) for failure

• Rear Exhaust has a major leak of exhaust gases (7.1.2)


Advisory notice item(s)

- Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

What are failures and advisories?



- Advisory notice item(s)
- Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Offside Front Tyre worn close to the legal limit (4.1.E.1)



Check for vehicle recalls

See if VOLKSWAGEN SHARAN EY55OUD has outstanding recalls

✓ Show

<u>Cookies</u> <u>Terms and conditions</u> <u>Privacy notice</u> <u>Accessibility statement</u> <u>MOT history API</u> <u>Service status</u>

Built by the Driver & Vehicle Standards Agency

OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

© Crown copyright