



- ① Main entrance relocated to face car park. New external canopy created with signage over new entrance. External lighting to underside of canopy.
- ② Existing wall externally insulated and rendered for improvement of thermal performance. Windows upgraded throughout.
- ③ High-level metal cladding replaced throughout and insulation added.
- ④ Cladding and windows to spin studio upgraded.

Visualisation of New Entrance