



Check MOT history (<https://www.gov.uk/check-mot-history>)

WR10NUP

## KIA CEED

Colour

**Silver**

Fuel type

**Diesel**

Date registered

**19 May 2010**

MOT valid until

**21 September 2020**

### MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested

**3 September 2019**

**PASS**

Mileage

**126,872 miles**

Test location

MOT test number

**5040 3780 3804**

Expiry date

**21 September 2020**

Monitor and repair if necessary (advisories):

- **Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**
- **Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**

Date tested

**24 August 2019**

**FAIL**

Mileage

**126,500 miles**

Test location

MOT test number

**3624 7411 0040**

Repair immediately (major defects):

- **Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush**

**(5.3.4 (a) (i))**

- **Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**

Date tested  
**22 September 2018**

**PASS**

Mileage  
**114,694 miles**

Test location

MOT test number  
**7831 7805 7079**

Expiry date  
**21 September 2019**

Monitor and repair if necessary (advisories):

- **rear Trailing arm bushes perishing**
- **Nearside Rear Service brake binding but not excessively (1.2.1 (f))**

Date tested  
**15 September 2018**

**FAIL**

Mileage  
**114,374 miles**

Test location

MOT test number  
**1141 9120 0418**

Repair immediately (major defects):

- **Front Brakes imbalanced across an axle (1.2.1 (b) (i))**
- **Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**
- **Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **rear Trailing arm bushes perishing**
- **Nearside Rear Service brake binding but not excessively (1.2.1 (f))**

### The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested  
**6 September 2017**

**PASS**

Mileage  
**100,233 miles**

Test location

MOT test number  
**9622 0914 5444**

Expiry date  
**21 September 2018**

Advisory notice item(s)

- **Offside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)**

Date tested  
**4 September 2017**

**FAIL**

Mileage  
**100,095 miles**

MOT test number  
**4421 9386 8775**

Test location

Reason(s) for failure

- **Nearside Front Upper Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**
- **Offside Front Upper Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**
- **Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**

Advisory notice item(s)

- **Offside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)**

Date tested  
**9 September 2016**

**PASS**

Mileage  
**86,207 miles**

MOT test number  
**2393 6212 9902**

Test location

Expiry date  
**21 September 2017**

Advisory notice item(s)

- **Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**

Date tested  
**11 September 2015**

**PASS**

Mileage  
**69,757 miles**

MOT test number  
**6690 8095 2078**

Test location

Expiry date  
**21 September 2016**

Date tested  
**22 September 2014**

**PASS**

Mileage  
**53,242 miles**

MOT test number  
**5954 3596 4295**

Test location

Expiry date  
**21 September 2015**

Date tested  
**9 May 2013**

Mileage  
**48,125 miles**

MOT test number  
**7597 6972 3117**

# PASS

Test location

Expiry date  
**19 May 2014**

---

## Outstanding vehicle recalls

Check if KIA CEED WR10NUP has outstanding recalls

---