

Check MOT history (https://www.gov.uk/check-mot-history)

EY550UD

VOLKSWAGEN SHARAN

Colour Fuel type Date registered

Black Diesel 1 September 2005

MOT valid until

7 January 2022

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested

16 December 2020

PASS

Mileage

200,204 miles

MOT test number

9001 8048 9517

Test location

Expiry date

7 January 2022

Date tested

28 June 2019

PASS

Mileage

169,053 miles

MOT test number

6500 1274 2630

Test location Expiry date

7 January 2021

Monitor and repair if necessary (advisories):

- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Date tested

28 June 2018

PASS

Mileage

127,446 miles

MOT test number

1060 4352 0676

Test location

Expiry date

7 July 2019

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
5 July 2017
PASS

Mileage **94,571 miles**

MOT test number **7976 7775 8274**

Test location

Expiry date 7 July 2018

Date tested 6 July 2016 PASS Mileage **81,974 miles**

MOT test number **4962 9545 3816**

Test location

Expiry date **7 July 2017**

Date tested
3 July 2015
PASS

Mileage **72,496 miles**

MOT test number **7472 1478 5117**

Test location

Expiry date 7 July 2016

Date tested 8 July 2014 PASS Mileage **61,555 miles**

MOT test number **2398 4928 4108**

Test location

Expiry date 7 July 2015

Advisory notice item(s)

- Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Date tested
7 July 2014
FAIL

Mileage **61,555 miles**

MOT test number **5759 2898 4135**

Test location

Reason(s) for failure

• Rear Exhaust has a major leak of exhaust gases (7.1.2)

Advisory notice item(s)

 Nearside Front Tyre worn close to the legal limit (4.1.E.1)

•	Offside Front Tyre worn close to the legal limit
	(4.1.E.1)

 Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Date tested 26 June 2013 PASS

Mileage **51,452 miles**

MOT test number **9570 5777 3165**

Test location

Expiry date 7 July 2014

Date tested 6 July 2012 PASS

Mileage **42,761 miles**

MOT test number **3367 1818 2148**

Test location Expiry date

7 July 2013

Advisory notice item(s)

 Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

• nearside rear tyre cracking on outer sidewall

• Spare tyre defective

Date tested 8 July 2011 PASS

Mileage **37,867 miles**

MOT test number **3780 0948 1154**

Test location

Expiry date 7 July 2012

7 July 2010 PASS

Mileage **33.609 miles**

MOT test number 9802 3888 0121

Test location

Expiry date **7 July 2011**

Advisory notice item(s)

 Nearside Front Tyre worn close to the legal limit (4.1.E.1)

• Offside Front Tyre worn close to the legal limit (4.1.E.1)

Date tested
7 July 2009
PASS

Mileage **29,587 miles**

MOT test number **9537 9828 9154**

Test location

Expiry date 7 July 2010



Mileage **22,761 miles**

Test location

MOT test number **2704 4099 8168**

Expiry date **7 July 2009**

Outstanding vehicle recalls

Check if VOLKSWAGEN SHARAN EY55OUD has outstanding recalls