

Check MOT history (<https://www.gov.uk/check-mot-history>)

RE11KFJ

FORD TRANSIT

Colour
Silver

Fuel type
Diesel

Date registered
11 July 2011

MOT valid until
17 February 2023

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested
18 February 2022

PASS

Mileage
271,908 miles

MOT test number
6647 2509 4229

Test location

Expiry date
17 February 2023

Monitor and repair if necessary (advisories):

- **Power steering notchy**
- **Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
- **Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
- **Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
- **Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
- **Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))**
- **Rear Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**

- **Central Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**
 - **Oil leak, but not excessive (8.4.1 (a) (i))**
 - **Play in steering rack inner joint(s) ()**
 - **Noise from engine**
-

Date tested
18 February 2022

FAIL

Mileage
271,908 miles

MOT test number
1759 8853 6316

Test location

Repair immediately (major defects):

- **Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**
- **Nearside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**

Monitor and repair if necessary (advisories):

- **Power steering notchy**
 - **Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
 - **Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
 - **Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
 - **Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
 - **Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**
 - **Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))**
 - **Rear Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**
 - **Central Brake pipe corroded, covered in grease or other material X2 (1.1.11 (c))**
 - **Oil leak, but not excessive (8.4.1 (a) (i))**
 - **Play in steering rack inner joint(s) ()**
 - **Noise from engine**
-

Date tested
31 January 2022

Mileage
271,867 miles

MOT test number
2285 3440 3946

FAIL

Test location

Repair immediately (major defects):

- **Nearside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**
- **Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**
- **Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**
- **Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength crossmember (5.3.6 (a) (i))**
- **Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**
- **Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**
- **Central Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))**
- **Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**

Repair as soon as possible (minor defects):

- **Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**

Monitor and repair if necessary (advisories):

- **both front steps corroded and hold**
- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
- **Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**
- **Noise from engine**

- **Rear wheel arches corroded**
- **Nearside Front Wheel arch corroded and hold**
- **Tail gate inner trim cover missing**
- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Nearside Front Play in steering rack inner joint(s) ()**
- **Offside Front Play in steering rack inner joint(s) ()**
- **Corroded Front and rear**

Date tested
3 February 2021

PASS

Mileage
250,071 miles

MOT test number
6041 2281 9003

Test location

Expiry date
2 February 2022

Monitor and repair if necessary (advisories):

- **Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**
- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

Date tested
9 April 2019

PASS

Mileage
210,237 miles

MOT test number
2052 9596 2484

Test location

Expiry date
16 October 2020

Monitor and repair if necessary (advisories):

- **Front Brake disc worn, but not excessively (1.1.14 (a) (i))**

Date tested
9 April 2019

FAIL

Mileage
210,237 miles

MOT test number
7278 5428 0287

Test location

Repair immediately (major defects):

- **Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**
- **Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**

Repair as soon as possible (minor defects):

- **Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**

- **Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**

Monitor and repair if necessary (advisories):

- **Front Brake disc worn, but not excessively (1.1.14 (a) (i))**

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
11 April 2018
PASS

Mileage
178,939 miles

MOT test number
7898 0092 0593

Test location

Expiry date
16 April 2019

Date tested
11 April 2018
FAIL

Mileage
178,937 miles

MOT test number
4732 5541 0551

Test location

Reason(s) for failure

- **Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**
- **Offside Rear Direction indicator incorrect colour (1.4.A.2f)**
- **Nearside Rear Electrical wiring insecure brake sensor (1.9.2a)**
- **Offside Track rod end ball joint has excessive play (2.2.B.1f)**

Advisory notice item(s)

- **Nearside Rear Brake pad(s) wearing thin (3.5.1g)**
- **service light displayed on dash**

Date tested
17 April 2017
PASS

Mileage
155,196 miles

MOT test number
8112 1667 3139

Test location

Expiry date
16 April 2018

Advisory notice item(s)

- **Nearside Front tyre getting close to limit**
 - **Offside Front tyre getting close to limit**
-

Date tested
14 April 2017

FAIL

Mileage
155,196 miles

Test location

MOT test number
6314 9317 3348

Reason(s) for failure

- **Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement antiroll bar d bush (2.4.G.2)**

Advisory notice item(s)

- **Nearside Front tyre getting close to limit**
 - **Offside Front tyre getting close to limit**
-

Date tested
11 March 2016

PASS

Mileage
129,138 miles

Test location

MOT test number
5087 0148 6128

Expiry date
10 March 2017

Date tested
13 July 2015

PASS

Mileage
118,218 miles

Test location

MOT test number
1577 5469 5124

Expiry date
12 July 2016

Date tested
20 June 2014

PASS

Mileage
81,115 miles

Test location

MOT test number
3668 3167 4118

Expiry date
11 July 2015

Date tested
20 June 2014

FAIL

Mileage
81,115 miles

Test location

MOT test number
8187 5167 4193

Reason(s) for failure

- **Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**
-

Outstanding vehicle recalls

Check if FORD TRANSIT RE11KFJ has outstanding recalls
