

Check MOT history (<https://www.gov.uk/check-mot-history>)

BV12HGG

FORD GALAXY

Colour
White

Fuel type
Diesel

Date registered
20 March 2012

MOT valid until
20 March 2023

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested
8 March 2022

PASS

Mileage
295,848 miles

Test location

MOT test number
8678 8584 5715

Expiry date
20 March 2023

Repair as soon as possible (minor defects):

- **Offside Obligatory mirror slightly damaged (3.3 (b) (i))**

Date tested
8 March 2022

FAIL

Mileage
295,848 miles

Test location

MOT test number
7260 5961 9524

Do not drive until repaired (dangerous defects):

- **Nearside Rear Tyre tread depth below requirements of 1.6mm 225-50-17 (5.2.3 (e))**

Repair immediately (major defects):

- **Nearside Front Headlamp insecure (4.1.1 (c))**
- **Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction**
Phone holder (3.1 (a) (ii))
- **Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b))**

- (ii)
- **Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**

Repair as soon as possible (minor defects):

- **Offside Obligatory mirror slightly damaged (3.3 (b) (i))**
- **Windscreen wiper blade defective Smearing (3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Brake pad(s) wearing thin All (1.1.13 (a) (ii))**

Date tested
10 March 2021

PASS

Mileage
277,416 miles

MOT test number
7043 6496 5970

Test location

Expiry date
20 March 2022

Repair as soon as possible (minor defects):

- **Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**
- **Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**

Date tested
9 March 2020

PASS

Mileage
264,889 miles

MOT test number
2160 6664 7837

Test location

Expiry date
20 March 2021

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm 225/50 17 (5.2.3 (e))**

- **Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**

Date tested
9 March 2020

FAIL

Mileage
264,889 miles

MOT test number
1568 7455 8946

Test location

Repair immediately (major defects):

- **Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm 225/50 17 (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**

Date tested
21 March 2019

PASS

Mileage
223,630 miles

MOT test number
7265 0325 0358

Test location

Expiry date
20 March 2020

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Date tested
20 March 2019

FAIL

Mileage
223,589 miles

MOT test number
2889 4813 5910

Test location

Do not drive until repaired (dangerous defects):

- **Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**
- **Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Repair immediately (major defects):

- **Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))**

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Tyre worn close to legal limit/worn on edge Tyres badly worn inner edge, close to cord being exposed (5.2.3 (e))**
- **Rear Nail in tyre Both rear tyres ()**

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
6 March 2018

PASS

Mileage
184,361 miles

Test location

MOT test number
6094 5726 7965

Expiry date
20 March 2019

Date tested
17 March 2017

PASS

Mileage
142,664 miles

Test location

MOT test number
8613 0105 8130

Expiry date
20 March 2018

Advisory notice item(s)

- **Front Brake pad(s) wearing thin (3.5.1g)**
- **Rear Brake pad(s) wearing thin (3.5.1g)**
- **Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**
- **Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**
- **Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Rear tyres worn more on inner edges**
- **Nearside Rear tyre out of shape**
- **Nearside Rear small cut in tread of tyre**

Date tested
9 March 2016

Mileage
108,577 miles

MOT test number
8122 8299 3765

PASS

Test location

Expiry date

20 March 2017

Advisory notice item(s)

- **Rear seats folded, could not check seat belts.**
 - **Offside Front Inner tie rod end has play.**
-

Date tested

12 March 2015

PASS

Mileage

81,752 miles

MOT test number

8653 1177 5012

Test location

Expiry date

20 March 2016

Advisory notice item(s)

- **Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
 - **Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**
-

Outstanding vehicle recalls

Check if FORD GALAXY BV12HGG has outstanding recalls
