

Tell us whether you accept cookies

We use [cookies to collect information \(/cookies\)](/cookies) about how you use the MOT history service. We use this information to make the service work as well as possible.

[Set cookie preferences \(/cookie-preferences\)](/cookie-preferences)



Check MOT history (<https://www.gov.uk/check-mot-history>)

KV09WPK

MERCEDES-BENZ E

Colour	Fuel type	Date registered
Silver	Diesel	30 March 2009

MOT valid until
26 April 2023

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested	Mileage	MOT test number
30 March 2022	289,676 miles	7757 4608 7269

PASS

Test location	Expiry date
	26 April 2023

Date tested	Mileage	MOT test number
28 March 2022	289,671 miles	9098 2426 3748

FAIL

Test location

Repair immediately (major defects):

- **Offside Headlamp not working on main beam (4.1.1 (a) (ii))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

Date tested
15 April 2021
PASS

Mileage
273,896 miles

MOT test number
4011 6374 8686

Test location

Expiry date
26 April 2022

Date tested
10 April 2021
FAIL

Mileage
273,896 miles

MOT test number
5035 8647 8208

Test location

Do not drive until repaired (dangerous defects):

- **Front Fuel system component leaking excessively or a risk of fire (6.1.3 (b) (ii))**

Repair immediately (major defects):

- **Front Fuel hose leaking (6.1.3 (b) (i))**
- **Rear Headlamp levelling device inoperative (4.1.5 (a))**
- **Headlamp aim not tested (4.1.2 (b))**

Monitor and repair if necessary (advisories):

- **Offside Front Play in steering rack inner joint(s) ()**
- **Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**

Date tested
27 April 2020
PASS

Mileage
270,141 miles

MOT test number
4420 3475 7589

Test location

Expiry date
26 April 2021

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**

Date tested
27 April 2020

FAIL

Mileage
270,141 miles

MOT test number
5431 1841 3310

Test location

Repair immediately (major defects):

- **Offside Front Headlamp light intensity severely reduced (4.1.4 (a))**
- **Offside Front Lower Suspension arm ball joint excessively worn spring control arm ball joint (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**

Date tested
24 April 2019

PASS

Mileage
246,021 miles

MOT test number
6563 7835 1693

Test location

Expiry date
23 October 2020

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
15 May 2018

PASS

Mileage
216,168 miles

MOT test number
5222 3915 9149

Test location

Expiry date

10 June 2019

Date tested
15 May 2017

PASS

Mileage
179,313 miles

Test location

MOT test number
7519 2056 6625

Expiry date
10 June 2018

Date tested
15 May 2017

FAIL

Mileage
179,312 miles

Test location

MOT test number
9712 4811 5684

Reason(s) for failure

- **Offside Windscreen washer provides insufficient washer liquid (8.2.3)**
- **rear parking (secondary) brakes imbalanced (3.7.B.6b)**

Date tested
25 May 2016

PASS

Mileage
142,083 miles

Test location

MOT test number
3507 1486 1072

Expiry date
10 June 2017

Advisory notice item(s)

- **Front Brake disc's worn.**
- **Offside Front wheel bearing has slight play (2.5.A.3c)**

Date tested
19 May 2016

FAIL

Mileage
141,936 miles

Test location

MOT test number
3667 7533 2886

Reason(s) for failure

- **Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**
- **Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**
- **Nearside Headlamp incorrect colour pink (1.7.5b)**

Advisory notice item(s)

- **Front Brake disc's worn.**
- **Offside Front wheel bearing has slight play (2.5.A.3c)**

Date tested
18 May 2015
PASS

Mileage
106,735 miles

Test location

MOT test number
3875 5863 5190

Expiry date
10 June 2016

Advisory notice item(s)

- **Items removed from driver's view prior to test**

Date tested
22 May 2014
PASS

Mileage
58,703 miles

Test location

MOT test number
3372 9284 4109

Expiry date
10 June 2015

Advisory notice item(s)

- **nearside rear tyre down to 2 mm**

Date tested
11 June 2013
PASS

Mileage
16,354 miles

Test location

MOT test number
6753 8236 3175

Expiry date
10 June 2014

Date tested
18 May 2012
PASS

Mileage
13,058 miles

Test location

MOT test number
7498 5913 2105

Expiry date
17 May 2013

Outstanding vehicle recalls

Check if MERCEDES-BENZ E KV09WPK has outstanding recalls
