

Check MOT history

This is a new service – [Complete a quick survey \(https://www.smartsurvey.co.uk/s/GIZZX?vrn=OV62YPG&make_result=MERCEDES-BENZ&model_result=C&mot_first_used_date=2012-11-29&vehicle_age=3729&mot_expiry_date=2024-02-05&mot_expiry_date_days_left=356&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrn=OV62YPG&make_result=MERCEDES-BENZ&model_result=C&mot_first_used_date=2012-11-29&vehicle_age=3729&mot_expiry_date=2024-02-05&mot_expiry_date_days_left=356&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) to help us improve.

[< Back](#)

OV62 YPG MERCEDES-BENZ C

[Check another vehicle \(/\)](#)

Colour

Black

Fuel type

Diesel

Date registered

29 November 2012

MOT valid until

5 February 2024

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-v5c?registration=OV62YPG\)](/enter-v5c?registration=OV62YPG)

If you think the MOT expiry date or any of the vehicle details are wrong: [contact DVSA \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).

[^ Hide all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[^ Hide](#)

Date tested

6 February 2023

PASS

Mileage

227,415 miles

Test location

▶ [View test location](#)

MOT test number

3421 2858 0588

Expiry date

5 February 2024

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Play in steering rack inner joint(s)**

▶ [What are advisories?](#)

Date tested

6 February 2023

FAIL

Mileage

227,412 miles

Test location

▶ [View test location](#)

MOT test number

3278 3990 8676

Repair immediately (major defects):

- **Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Play in steering rack inner joint(s)**

▶ [What are defects and advisories?](#)

Date tested

19 January 2022

PASS

Mileage

183,265 miles

Test location

▶ [View test location](#)

MOT test number

2862 4362 8113

Expiry date

18 January 2023

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**

▶ [What are advisories?](#)

Date tested

18 January 2022

FAIL

Mileage

183,099 miles

Test location

▶ [View test location](#)

MOT test number

9766 2713 7853

Repair immediately (major defects):

- **Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Nearside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**
- **Offside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**

▶ [What are defects and advisories?](#)

Date tested

15 January 2021

PASS

Mileage

155,982 miles

Test location

▶ [View test location](#)

MOT test number

3659 7846 6426

Expiry date

15 January 2022

Date tested

6 January 2020

PASS

Mileage

149,884 miles

Test location

▶ [View test location](#)

MOT test number

9780 9912 9981

Expiry date

15 January 2021

Repair as soon as possible (minor defects):

- **Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Rear parking brake imbalance**

▶ [What are advisories?](#)

Date tested

30 December 2019

FAIL

Mileage

149,357 miles

Test location

▶ [View test location](#)

MOT test number

9877 9969 0484

Repair immediately (major defects):

- **Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**
- **Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**

Repair as soon as possible (minor defects):

- **Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**

▶ [What are defects and advisories?](#)

Date tested

2 January 2019

PASS

Mileage

109,020 miles

Test location

▶ [View test location](#)

MOT test number

3323 6388 1135

Expiry date

15 January 2020

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre wearing on outer edge**
- **Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**

▶ [What are advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested

5 January 2018

PASS

Mileage

88,605 miles

Test location

▶ [View test location](#)

MOT test number

3086 3878 7769

Expiry date

15 January 2019

Advisory notice item(s)

- **Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Offside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Nearside Front Advise : tyre sidewall damaged**

▶ [What are advisories?](#)

Date tested

9 January 2017

PASS

Mileage

76,705 miles

Test location

▶ [View test location](#)

MOT test number

8698 4569 9723

Expiry date

15 January 2018

Date tested

16 January 2016

PASS

Mileage

57,459 miles

Test location

▶ [View test location](#)

MOT test number

3407 6746 9116

Expiry date

15 January 2017

Advisory notice item(s)

- **Under-trays fitted obscuring some underside components**

▶ [What are advisories?](#)

Outstanding vehicle recalls

Check if MERCEDES-BENZ C OV62YPG has outstanding recalls

⤴ [Hide](#)

Outstanding recall found

This vehicle has been recalled since at least **10 February 2023**.

Contact a **MERCEDES-BENZ** dealership to arrange for repairs.

If you've had the recalled component repaired recently, it can take up to 3 weeks for the manufacturer to update their records.

This information is provided by the vehicle manufacturer. If you think the information is wrong, contact the vehicle manufacturer's dealership. Please do not contact the DVSA, as we are not able to change the recall status.

[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)
[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#).

OGI

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)