## GOV.UK

## **Check MOT history**

This is a new service — <u>Complete a quick survey (https://www.smvrm=CV11AXN&make\_result=FORD&model\_result=MONDEO&mot\_fi 30&vehicle\_age=4374&mot\_expiry\_date=2024-03-28&mot\_expiry\_date\_days\_left=373&user\_satisfaction\_banner=0&veh to help us improve.</u>

< Back

# CVII AXN FORD MONDEO

Check another vehicle (/)

Colour

**Blue** 

Fuel type

**Diesel** 

Date registered

30 March 2011

MOT valid until

28 March 2024

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-v5c?registration=CV11AXN)

If you think the MOT expiry date or any of the vehicle details are wrong: <a href="mailto:contact\_DVSA">contact\_DVSA</a> (<a href="https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes">https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes</a>).



## **MOT** history

Check mileage recorded at test, expiry date, and test outcome



Date tested **20 March 2023** 



Mileage 299,964 miles

Test location

View test location

MOT test number 1905 2959 9834

Expiry date
28 March 2024

#### 20 March 2023



Mileage 299,964 miles

**Test location** 

View test location

MOT test number

9873 9001 1453

Repair immediately (major defects):

- Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- What are defects?

Date tested

17 March 2022



Mileage

268,083 miles

**Test location** 

View test location

MOT test number

4936 7682 8108

Expiry date

Date tested

16 March 2022



Mileage

268,083 miles

**Test location** 

View test location

MOT test number

4335 7672 6612

Do not drive until repaired (dangerous defects):

 Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Repair immediately (major defects):

- Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Offside Front Position lamp not working (4.2.1 (a) (ii))
- Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Nearside Front All direction indicators incorrect colour (4.4.3 (a))
- Offside Front All direction indicators incorrect colour (4.4.3 (a))
- Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- What are defects?

#### 29 March 2021

## **PASS**

Mileage 248,695 miles

**Test location** 

View test location

MOT test number 8779 7263 9130

Expiry date

28 March 2022

Monitor and repair if necessary (advisories):

- Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- What are advisories?

Date tested

29 March 2021



Mileage

248,695 miles

**Test location** 

View test location

#### MOT test number

#### 7847 7846 4957

Repair immediately (major defects):

- Offside Front Position lamp not working (4.2.1 (a) (ii))
- Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Monitor and repair if necessary (advisories):

- Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Rear exhaust mount broken
- Front number plate in poor state
- What are defects and advisories?

Date tested 18 June 2020



Mileage 247,944 miles

**Test location** 

View test location

MOT test number 1856 0883 2463

Expiry date 17 June 2021

Monitor and repair if necessary (advisories):

- Front number plate in poor state
- What are advisories?

Date tested

4 June 2020



Mileage

247,944 miles

**Test location** 

View test location

MOT test number

7129 5887 9084

Repair immediately (major defects):

- Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Repair as soon as possible (minor defects):

 Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Front disc worn

- Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Front number plate in poor state
- What are defects and advisories?

Date tested

27 March 2019



Mileage

222,087 miles

**Test location** 

View test location

MOT test number

1867 8664 4383

Expiry date

4 June 2020

Monitor and repair if necessary (advisories):

- Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Oil leak, but not excessive (8.4.1 (a) (i))
- What are advisories?

## The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. Find out more

(https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested 27 March 2018

## **PASS**

Mileage 180,966 miles

**Test location** 

View test location

MOT test number 2249 0434 9269

Expiry date 1 April 2019

Date tested **22 March 2017** 

**PASS** 

Mileage 139,966 miles

**Test location** 

View test location

MOT test number 8639 8775 1589

**Expiry date** 

#### 1 April 2018

Advisory notice item(s)

- front brake discs wearing thin
- rear brake discs wearing thin
- Rear Brake pad(s) wearing thin (3.5.1g)
- Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- What are advisories?

Date tested

2 April 2016



Mileage 101,298 miles

**Test location** 

View test location

MOT test number 9849 3003 7320

Expiry date 1 April 2017

Advisory notice item(s)

- Rear Brake pad(s) wearing thin (3.5.1g)
- Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- What are advisories?

# Date tested 20 March 2015

# **PASS**

Mileage 58,107 miles

**Test location** 

View test location

MOT test number **1872 3917 5427** 

Expiry date 30 March 2016

Date tested 28 March 2014

# **PASS**

Mileage 42,990 miles

**Test location** 

View test location

MOT test number **3763 2798 4032** 

Expiry date 30 March 2015

### Check for vehicle recalls

See if FORD MONDEO CV11AXN has outstanding recalls



Cookies Terms and conditions
Privacy notice
Accessibility statement
MOT history API Service status

Built by the <u>Driver & Vehicle Standards</u> <u>Agency</u>

#### **OGL**

All content is available under the <u>Open</u> <u>Government Licence v3.0</u>, except where otherwise stated

© Crown copyright