

## Check MOT history

This is a new service – [Complete a quick survey \(https://www.smartsurvey.co.uk/s/GIZZX?vrn=BV12HGG&make\\_result=FORD&model\\_result=GALAXY&mot\\_first\\_used\\_date=2012-03-20&vehicle\\_age=4056&mot\\_expiry\\_date=2024-03-23&mot\\_expiry\\_date\\_days\\_left=330&user\\_satisfaction\\_banner=0&vehicle\\_data\\_origin=MTS&vehicle\\_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrn=BV12HGG&make_result=FORD&model_result=GALAXY&mot_first_used_date=2012-03-20&vehicle_age=4056&mot_expiry_date=2024-03-23&mot_expiry_date_days_left=330&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) to help us improve.

[< Back](#)

We need your help

Help us improve this service. [Complete a quick survey.](#)

**BV12 HGG**

# FORD GALAXY

[Check another vehicle \(/\)](#)

Colour

**White**

Fuel type

**Diesel**

Date registered

**20 March 2012**

MOT valid until

**23 March 2024**

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-v5c?registration=BV12HGG\)](/enter-v5c?registration=BV12HGG)

If you think the MOT expiry date or any of the vehicle details are wrong: [contact DVSA \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).

[⌵ Show all sections](#)

## MOT history

Check mileage recorded at test, expiry date, and test outcome

[⌶ Hide](#)

Date tested

24 March 2023

**PASS**

Mileage

**326,824 miles**

Test location

▶ [View test location](#)

MOT test number

**7955 3224 7415**

Expiry date

**23 March 2024**

---

Date tested

**24 March 2023**

**FAIL**

Mileage

**326,823 miles**

Test location

▶ [View test location](#)

MOT test number

**6449 6176 0852**

Do not drive until repaired (dangerous defects):

- **Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**

Repair immediately (major defects):

- **Headlamp insecure Both (4.1.1 (c))**
- **Headlamp aim unable to be tested (4.1.2 (b))**
- **Nearside Front Position lamp not working (4.2.1 (a) (ii))**
- **Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**

▶ [What are defects?](#)

---

Date tested

**8 March 2022**

**PASS**

Mileage

**295,848 miles**

Test location

▶ [View test location](#)

MOT test number

**8678 8584 5715**

Expiry date

**20 March 2023**

Repair as soon as possible (minor defects):

- **Offside Obligatory mirror slightly damaged (3.3 (b) (i))**

▶ [What are defects and advisories?](#)

---

Date tested

**8 March 2022**

**FAIL**

Mileage

**295,848 miles**

Test location

▶ [View test location](#)

MOT test number

**7260 5961 9524**

Do not drive until repaired (dangerous defects):

- **Nearside Rear Tyre tread depth below requirements of 1.6mm 225-50-17 (5.2.3 (e))**

Repair immediately (major defects):

- **Nearside Front Headlamp insecure (4.1.1 (c))**
- **Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction Phone holder (3.1 (a) (ii))**
- **Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**

Repair as soon as possible (minor defects):

- **Offside Obligatory mirror slightly damaged (3.3 (b) (i))**
- **Windscreen wiper blade defective Smearing (3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Brake pad(s) wearing thin All (1.1.13 (a) (ii))**

▶ [What are defects and advisories?](#)

---

Date tested

**10 March 2021**

**PASS**

Mileage

**277,416 miles**

Test location

▶ [View test location](#)

MOT test number

**7043 6496 5970**

Expiry date

**20 March 2022**

Repair as soon as possible (minor defects):

- **Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**
- **Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**

▶ [What are advisories?](#)

---

Date tested

**9 March 2020**

**PASS**

Mileage

**264,889 miles**

Test location

▶ [View test location](#)

MOT test number

**2160 6664 7837**

Expiry date

**20 March 2021**

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm 225/50 17 (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**

▶ [What are advisories?](#)

---

Date tested

**9 March 2020**

**FAIL**

Mileage

**264,889 miles**

Test location

▶ [View test location](#)

MOT test number

**1568 7455 8946**

Repair immediately (major defects):

- **Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm 225/50 17 (5.2.3 (e))**

- **Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**

▶ [What are defects and advisories?](#)

---

Date tested

**21 March 2019**

**PASS**

Mileage

**223,630 miles**

Test location

▶ [View test location](#)

MOT test number

**7265 0325 0358**

Expiry date

**20 March 2020**

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

▶ [What are defects and advisories?](#)

---

Date tested

**20 March 2019**

**FAIL**

Mileage

**223,589 miles**

Test location

▶ [View test location](#)

MOT test number

**2889 4813 5910**

Do not drive until repaired (dangerous defects):

- **Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**
- **Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Repair immediately (major defects):

- **Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))**

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Tyre worn close to legal limit/worn on edge Tyres badly worn inner edge, close to cord being exposed (5.2.3 (e))**
- **Rear Nail in tyre Both rear tyres**

▶ [What are defects and advisories?](#)

---

## The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

---

Date tested

**6 March 2018**

**PASS**

Mileage

**184,361 miles**

Test location

▶ [View test location](#)

MOT test number

**6094 5726 7965**

Expiry date

**20 March 2019**

---

Date tested

**17 March 2017**

**PASS**

Mileage

**142,664 miles**

Test location

▶ [View test location](#)

MOT test number

**8613 0105 8130**

Expiry date

**20 March 2018**

Advisory notice item(s)

- **Front Brake pad(s) wearing thin (3.5.1g)**
- **Rear Brake pad(s) wearing thin (3.5.1g)**
- **Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**
- **Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**
- **Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Rear tyres worn more on inner edges**
- **Nearside Rear tyre out of shape**
- **Nearside Rear small cut in tread of tyre**

▶ [What are advisories?](#)

---

Date tested

**9 March 2016**

# PASS

Mileage

**108,577 miles**

Test location

▶ [View test location](#)

MOT test number

**8122 8299 3765**

Expiry date

**20 March 2017**

Advisory notice item(s)

- **Rear seats folded, could not check seat belts.**
- **Offside Front Inner tie rod end has play.**

▶ [What are advisories?](#)

---

Date tested

**12 March 2015**

# PASS

Mileage

**81,752 miles**

Test location

▶ [View test location](#)

MOT test number

**8653 1177 5012**

Expiry date

**20 March 2016**

Advisory notice item(s)

- **Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**
- **Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**

▶ [What are advisories?](#)

---

## Check for vehicle recalls

See if FORD GALAXY BV12HGG has outstanding recalls

⌵ [Show](#)

---

[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)

[MOT history API](#) [Service status](#)

Built by the Driver & Vehicle Standards Agency

**OGI**

All content is available under the Open Government Licence v3.0, except where otherwise stated

© Crown copyright