# Check MOT history

This is a new service – <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX?</u> <u>vrm=KV09WPK&make\_result=MERCEDES-BENZ&model\_result=E&mot\_first\_used\_date=2009-03-</u> <u>30&vehicle\_age=5175&mot\_expiry\_date=2024-04-</u> <u>26&mot\_expiry\_date\_days\_left=331&user\_satisfaction\_banner=0&vehicle\_data\_origin=MTS&vehicle\_type=LGV</u>) to help us improve.

< <u>Back</u>

# кV09 WPK MERCEDES-BENZ E

Check another vehicle (/)

Colour Silver

Fuel type **Diesel** 

Date registered 30 March 2009

MOT valid until

# 26 April 2024

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-v5c?registration=KV09WPK)

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA</u> (<u>https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes</u>).

→ Hide all sections

## **MOT** history

Check mileage recorded at test, expiry date, and test outcome

Date tested 29 March 2023



Mileage 304,993 miles

**Test location** 

<u>View test location</u>
MOT test number
7124 8670 3493

Expiry date 26 April 2024

Date tested 27 March 2023



Mileage 304,934 miles

**Test location** 

View test location

MOT test number **1249 7940 2282** 

Repair immediately (major defects):

• Offside Front Suspension component ball joint excessively worn onto track control arm (5.3.4 (a) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))

What are defects and advisories?

Date tested 30 March 2022

PASS

Mileage 289,676 miles

**Test location** 

View test location

MOT test number 7757 4608 7269

Expiry date 26 April 2023

Date tested 28 March 2022

FAIL Mileage 289,671 miles

**Test location** 

#### View test location

MOT test number **9098 2426 3748** Repair immediately (major defects):

• Offside Headlamp not working on main beam (4.1.1 (a) (ii))

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- What are defects and advisories?

Date tested 15 April 2021



Mileage 273,896 miles

Test location

View test location

MOT test number 4011 6374 8686

Expiry date 26 April 2022

Date tested 10 April 2021



Mileage 273,896 miles

**Test location** 

View test location

MOT test number 5035 8647 8208

Do not drive until repaired (dangerous defects):

• Front Fuel system component leaking excessively or a risk of fire (6.1.3 (b) (ii))

Repair immediately (major defects):

- Front Fuel hose leaking (6.1.3 (b) (i))
- Rear Headlamp levelling device inoperative (4.1.5 (a))
- Headlamp aim not tested (4.1.2 (b))

Monitor and repair if necessary (advisories):

- Offside Front Play in steering rack inner joint(s)
- Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

• Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

What are defects and advisories?

Date tested 27 April 2020



Mileage 270,141 miles

Test location

View test location

MOT test number 4420 3475 7589

Expiry date 26 April 2021

Monitor and repair if necessary (advisories):

- Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- What are advisories?

Date tested 27 April 2020



Mileage 270,141 miles

**Test location** 

View test location

MOT test number 5431 1841 3310

Repair immediately (major defects):

- Offside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Offside Front Lower Suspension arm ball joint excessively worn spring control arm ball joint (5.3.4 (a) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

What are defects and advisories?

24 April 2019



246,021 miles

**Test location** 

View test location

MOT test number 6563 7835 1693

Expiry date 23 October 2020

#### The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out</u> <u>more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested 15 May 2018



Mileage 216,168 miles

**Test location** 

View test location

MOT test number 5222 3915 9149

Expiry date 10 June 2019

Date tested 15 May 2017

PASS

Mileage 179,313 miles

**Test location** 

View test location

MOT test number 7519 2056 6625

Expiry date 10 June 2018

Date tested 15 May 2017

FAIL Mileage 179,312 miles

**Test location** 

View test location

MOT test number 9712 4811 5684

Reason(s) for failure

- Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- rear parking (secondary) brakes imbalanced (3.7.B.6b)

What are failures?

Date tested 25 May 2016



Mileage 142,083 miles

**Test location** 

View test location

MOT test number 3507 1486 1072

Expiry date 10 June 2017

Advisory notice item(s)

- Front Brake disc's worn.
- Offside Front wheel bearing has slight play (2.5.A.3c)

What are advisories?

Date tested 19 May 2016



Mileage 141,936 miles

**Test location** 

View test location

MOT test number 3667 7533 2886

#### Reason(s) for failure

- Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Nearside Headlamp incorrect colour pink (1.7.5b)

Advisory notice item(s)

- Front Brake disc's worn.
- Offside Front wheel bearing has slight play (2.5.A.3c)
- What are failures and advisories?

Date tested 18 May 2015



Mileage 106,735 miles

Test location

View test location

MOT test number 3875 5863 5190

Expiry date **10 June 2016** 

Advisory notice item(s) • Items removed from driver's view prior to test

What are advisories?

Date tested 22 May 2014

PASS

Mileage 58,703 miles

**Test location** 

View test location

MOT test number 3372 9284 4109

Expiry date 10 June 2015

Advisory notice item(s)

- nearside rear tyre down to 2 mm
- What are advisories?

Date tested

11 June 2013



16,354 miles

**Test location** 

View test location

MOT test number 6753 8236 3175

Expiry date 10 June 2014

Date tested 18 May 2012



13,058 miles

Test location

View test location

MOT test number **7498 5913 2105** 

Expiry date **17 May 2013** 

### Check for vehicle recalls

See if MERCEDES-BENZ E KV09WPK has outstanding recalls

→ Hide

#### No recalls found.

This information is provided by the vehicle manufacturer. If you think the recall information is wrong, contact your local dealership.

<u>Cookies</u> <u>Terms and conditions</u> <u>Privacy notice</u> <u>Accessibility statement</u> <u>MOT history API</u> <u>Service status</u>

Built by the Driver & Vehicle Standards Agency

### OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

© Crown copyright