

Check MOT history

This is a new service – [Complete a quick survey \(https://www.smartsurvey.co.uk/s/GIZZX?vrn=EXZ599&make_result=MERCEDES-BENZ&model_result=S-Class&mot_first_used_date=2011-03-01&vehicle_age=4522&mot_expiry_date=2024-07-11&mot_expiry_date_days_left=359&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrn=EXZ599&make_result=MERCEDES-BENZ&model_result=S-Class&mot_first_used_date=2011-03-01&vehicle_age=4522&mot_expiry_date=2024-07-11&mot_expiry_date_days_left=359&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) to help us improve.

[< Back](#)

EXZ 599

MERCEDES-BENZ S-Class

[Check another vehicle \(/\)](#)

Colour

Silver

Fuel type

Diesel

Date registered

1 March 2011

MOT valid until

11 July 2024

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-v5c?registration=EXZ599\)](/enter-v5c?registration=EXZ599)

If you think the MOT expiry date or any of the vehicle details are wrong: [contact DVSA \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).

[⌵ Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[⌶ Hide](#)

Date tested

12 July 2023

PASS

Mileage

87,713 miles

Test location

▶ [View test location](#)

MOT test number
5039 6106 6943

Expiry date
11 July 2024

Date tested
21 April 2023

PASS

Mileage
86,816 miles

Test location

▶ [View test location](#)

MOT test number
8968 1087 2852

Expiry date
2 May 2024

Repair as soon as possible (minor defects):

- **Steering lock not functioning (7.3 (a))**
- **Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))**
- **Suspension component mounting prescribed area is corroded but not considered excessive both rear (5.3.6 (a) (i))**
- **Wheel bearing has slight play both front (5.1.3 (a) (i))**
- **various components corroding.**
- **Offside Rear Tyre worn close to legal limit/worn on edge on limit 1.6mm (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested
3 May 2022

PASS

Mileage
85,097 miles

Test location

▶ [View test location](#)

MOT test number
7920 6662 1856

Expiry date
2 May 2023

Repair as soon as possible (minor defects):

- **Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**
- **Offside Front Lower Window damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Front Brake disc worn, pitted or scored, but not seriously weakened both inner faces (1.1.14 (a) (ii))**
- **Rear Brake disc worn, pitted or scored, but not seriously weakened both inner faces (1.1.14 (a) (ii))**
- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested

29 April 2022

FAIL

Mileage

85,088 miles

Test location

▶ [View test location](#)

MOT test number

1189 6293 5769

Do not drive until repaired (dangerous defects):

- **Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**
- **Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**
- **Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**
- **Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**

▶ [What are defects and advisories?](#)

Date tested

16 April 2021

PASS

Mileage

74,189 miles

Test location

▶ [View test location](#)

MOT test number

7637 9286 2875

Expiry date

19 April 2022

Monitor and repair if necessary (advisories):

- **Offside Rear Road wheel fractured at bridge over valve (5.2.2 (a))**

▶ [What are advisories?](#)

Date tested

7 April 2021

FAIL

Mileage

74,005 miles

Test location

▶ [View test location](#)

MOT test number

2151 6800 5059

Do not drive until repaired (dangerous defects):

- **Offside Rear Road wheel has a welding defect (5.2.2 (a))**

▶ [What are defects?](#)

Date tested

20 April 2020

PASS

Mileage

69,318 miles

Test location

▶ [View test location](#)

MOT test number

2064 4797 7060

Expiry date

19 April 2021

Repair as soon as possible (minor defects):

- **Front Windscreen damaged but not adversely affecting driver's view chip X2 (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested

20 April 2020

FAIL

Mileage

69,318 miles

Test location

▶ [View test location](#)

MOT test number

9565 1623 9868

Repair immediately (major defects):

- **Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**

Repair as soon as possible (minor defects):

- **Front Windscreen damaged but not adversely affecting driver's view chip X2 (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))**

▶ [What are defects and advisories?](#)

Date tested

17 April 2019

PASS

Mileage

62,625 miles

Test location

▶ [View test location](#)

MOT test number

8254 4654 8015

Expiry date

16 October 2020

Repair as soon as possible (minor defects):

- **Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

▶ [What are defects and advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested

7 April 2018

PASS

Mileage

56,772 miles

Test location

▶ [View test location](#)

MOT test number

6189 8838 6870

Expiry date

8 April 2019

Date tested

8 April 2017

PASS

Mileage

47,749 miles

Test location

▶ [View test location](#)

MOT test number

8746 7096 0669

Expiry date

8 April 2018

Date tested

1 April 2016

PASS

Mileage

36,745 miles

Test location

▶ [View test location](#)

MOT test number

5323 7701 8990

Expiry date

8 April 2017

Date tested

9 April 2015

PASS

Mileage

26,922 miles

Test location

▶ [View test location](#)

MOT test number

2361 8949 5041

Expiry date
8 April 2016

Date tested
23 April 2014

PASS

Mileage
20,628 miles

Test location

▶ [View test location](#)

MOT test number
7368 3361 4111

Expiry date
22 April 2015

Check for vehicle recalls

See if MERCEDES-BENZ S-Class EXZ599 has outstanding recalls

⌵ [Show](#)

[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)

[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#).

OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

© [Crown copyright](#)