

Check MOT history

This is a new service — <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX? vrm=DY63KYA&make_result=VAUXHALL&model_result=ZAFIRA&mot_first_used_date=2013-09-30&vehicle_age=3721&mot_expiry_date=2024-12-</u>

<u>06&mot_expiry_date_days_left=364&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV</u>) to help us improve.

< Back

DY63 KYA

VAUXHALL ZAFIRA

Check another vehicle (/)

Colour Fuel type Date registered

Blue Petrol 30 September 2013

MOT valid until

6 December 2024

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

<u>Download test certificates (/enter-document-reference?registration=DY63KYA)</u>

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).</u>

Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

Hide

Date tested

17 November 2023

PASS

Mileage 170,195 miles MOT test number **2052 6028 8289**

Test location

Expiry date

View test location

6 December 2024

Repair as soon as possible (minor defects):

 Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Monitor and repair if necessary (advisories):

- Brake servo damaged but function not impaired corroded (1.1.3 (e))
- Oil leak, but not excessive (8.4.1 (a) (i))
- Oil leak, but not excessive (8.4.1 (a) (i))
- Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- slight play engine/gearbox mount
- ▶ What are advisories?

Date tested

13 November 2023

FAIL

Mileage 170,195 miles MOT test number **4831 8640 9676**

Test location

View test location

Do not drive until repaired (dangerous defects):

• Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Repair immediately (major defects):

- Brake pedal anti-slip provision worn smooth (1.1.2 (c))
- Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Repair as soon as possible (minor defects):

 Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Monitor and repair if necessary (advisories):

- Brake servo damaged but function not impaired corroded (1.1.3 (e))
- Oil leak, but not excessive (8.4.1 (a) (i))
- Oil leak, but not excessive (8.4.1 (a) (i))
- Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- slight play engine/gearbox mount
- ▶ What are defects and advisories?

Date tested **7 December 2022**

PASS

Mileage

162,539 miles

Test location

► View test location

MOT test number

5753 4050 1509

Expiry date

6 December 2023

- Nearside Rear tyre cracking
- Oil leak, but not excessive (8.4.1 (a) (i))

- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ► What are advisories?

Date tested **5 December 2022**

FAIL

Mileage 162,539 miles MOT test number **9780 1023 1838**

Test location

View test location

Repair immediately (major defects):

- Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Monitor and repair if necessary (advisories):

- Nearside Rear tyre cracking
- Oil leak, but not excessive (8.4.1 (a) (i))
- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- What are defects and advisories?

Date tested **17 November 2021**

PASS

Mileage 142,509 miles MOT test number **3145 4336 0577**

Test location

Expiry date

16 November 2022

View test location

Repair as soon as possible (minor defects):

 Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

- · rear exhaust heat shield insecure
- oil leak
- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- What are advisories?

Date tested

16 November 2021

FAIL

Mileage 142,509 miles MOT test number **2944 8376 8520**

Test location

▶ View test location

Repair immediately (major defects):

- Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Repair as soon as possible (minor defects):

 Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Monitor and repair if necessary (advisories):

- · rear exhaust heat shield insecure
- oil leak
- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- What are defects and advisories?

Date tested 13 November 2020



Mileage 113,960 miles MOT test number **5631 5925 1661**

Test location

Expiry date

View test location

12 November 2021

Repair as soon as possible (minor defects):

 Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- · Rear exhaust mount deteriorated
- ▶ What are advisories?

Date tested

13 November 2020

FAIL

Mileage 113,960 miles MOT test number **6280 8206 5740**

Test location

View test location

Repair immediately (major defects):

- Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Repair as soon as possible (minor defects):

 Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Monitor and repair if necessary (advisories):

- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- · Rear exhaust mount deteriorated
- ▶ What are defects and advisories?

Date tested 8 October 2019

PASS

Mileage 94,139 miles

MOT test number **2898 4512 3026**

Test location

Expiry date
7 October 2020

▶ View test location

- Oil leak, but not excessive (8.4.1 (a) (i))
- Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Date tested 4 October 2019



Mileage 94,139 miles

MOT test number 6737 4992 7718

Test location

View test location

Do not drive until repaired (dangerous defects):

 Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Repair immediately (major defects):

- Offside Rear Seat belt damaged (7.1.2 (b) (i))
- Offside Front Headlamp aim too high (4.1.2 (a))

Monitor and repair if necessary (advisories):

- Oil leak, but not excessive (8.4.1 (a) (i))
- Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ► What are defects and advisories?

Date tested 11 September 2018

PASS

Mileage 61,973 miles

Test location

► View test location

MOT test number **7599 0290 8003**

Expiry date

10 September 2019

Monitor and repair if necessary (advisories):

- Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Front n/s & o/s tyres wearing unevenly
- Offside Rear tyre wearing on edge
- ► What are advisories?

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested 29 August 2017

PASS

Mileage 32,196 miles

Test location

▶ View test location

MOT test number 4465 6912 7617

Expiry date 28 August 2018

Date tested **3 September 2016**

PASS

Mileage 22,241 miles

Test location

► <u>View test location</u>

MOT test number 8949 4703 8149

Expiry date **29 September 2017**

Check for vehicle recalls

See if VAUXHALL ZAFIRA DY63KYA has outstanding recalls



<u>Cookies Terms and conditions Privacy notice Accessibility statement MOT history API Service status</u>

Built by the **Driver & Vehicle Standards Agency**

OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

© Crown copyright