

## Check MOT history

This is a new service – [Complete a quick survey \(https://www.smartsurvey.co.uk/s/GIZZX?vrm=OV62YPG&make\\_result=MERCEDES-BENZ&model\\_result=C&mot\\_first\\_used\\_date=2012-11-29&vehicle\\_age=4101&mot\\_expiry\\_date=2025-02-18&mot\\_expiry\\_date\\_days\\_left=363&user\\_satisfaction\\_banner=0&vehicle\\_data\\_origin=MTS&vehicle\\_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrm=OV62YPG&make_result=MERCEDES-BENZ&model_result=C&mot_first_used_date=2012-11-29&vehicle_age=4101&mot_expiry_date=2025-02-18&mot_expiry_date_days_left=363&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) to help us improve.

[< Back](#)

**OV62 YPG**

# MERCEDES-BENZ C

[Check another vehicle \(/\)](#)

Colour  
**Black**

Fuel type  
**Diesel**

Date registered  
**29 November 2012**

MOT valid until  
**18 February 2025**

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-document-reference?registration=OV62YPG\)](/enter-document-reference?registration=OV62YPG)

If you think the MOT expiry date or any of the vehicle details are wrong: [contact DVSA \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).

[Show all sections](#)

## MOT history

Check mileage recorded at test, expiry date, and test outcome

[Hide](#)

Date tested  
**19 February 2024**

Mileage  
**255,702 miles**

MOT test number  
**6277 1860 5103**

**PASS**

Test location

[View test location](#)

Expiry date  
**18 February 2025**

Date tested  
**6 February 2023**

Mileage  
**227,415 miles**

MOT test number  
**3421 2858 0588**

# PASS

Test location

▶ [View test location](#)

Expiry date

**5 February 2024**

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Play in steering rack inner joint(s)**

▶ [What are advisories?](#)

---

Date tested

**6 February 2023**

Mileage

**227,412 miles**

MOT test number

**3278 3990 8676**

# FAIL

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Play in steering rack inner joint(s)**

▶ [What are defects and advisories?](#)

---

Date tested

**19 January 2022**

Mileage

**183,265 miles**

MOT test number

**2862 4362 8113**

# PASS

Test location

▶ [View test location](#)

Expiry date

**18 January 2023**

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**

▶ [What are advisories?](#)

---

Date tested  
18 January 2022

**FAIL**

Mileage  
183,099 miles

MOT test number  
9766 2713 7853

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Nearside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**
- **Offside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**

▶ [What are defects and advisories?](#)

---

Date tested  
15 January 2021

**PASS**

Mileage  
155,982 miles

MOT test number  
3659 7846 6426

Test location

▶ [View test location](#)

Expiry date  
15 January 2022

---

Date tested  
6 January 2020

**PASS**

Mileage  
149,884 miles

MOT test number  
9780 9912 9981

Test location

▶ [View test location](#)

Expiry date  
15 January 2021

Repair as soon as possible (minor defects):

- **Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Rear parking brake imbalance**

▶ [What are advisories?](#)

---

Date tested  
**30 December 2019**

Mileage  
**149,357 miles**

MOT test number  
**9877 9969 0484**

**FAIL**

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**
- **Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**

Repair as soon as possible (minor defects):

- **Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**
- **Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**

▶ [What are defects and advisories?](#)

---

Date tested  
**2 January 2019**

Mileage  
**109,020 miles**

MOT test number  
**3323 6388 1135**

**PASS**

Test location

Expiry date  
**15 January 2020**

▶ [View test location](#)

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre wearing on outer edge**
- **Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**

▶ [What are advisories?](#)

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

---

Date tested  
**5 January 2018**

**PASS**

Mileage  
**88,605 miles**

Test location

▶ [View test location](#)

MOT test number  
**3086 3878 7769**

Expiry date  
**15 January 2019**

Advisory notice item(s)

- **Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Offside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Nearside Front Advise : tyre sidewall damaged**

▶ [What are advisories?](#)

---

Date tested  
**9 January 2017**

**PASS**

Mileage  
**76,705 miles**

Test location

▶ [View test location](#)

MOT test number  
**8698 4569 9723**

Expiry date  
**15 January 2018**

---

Date tested  
**16 January 2016**

**PASS**

Mileage  
**57,459 miles**

Test location

▶ [View test location](#)

MOT test number  
**3407 6746 9116**

Expiry date  
**15 January 2017**

Advisory notice item(s)

- **Under-trays fitted obscuring some underside components**

▶ [What are advisories?](#)

---

## Check for vehicle recalls

See if MERCEDES-BENZ C OV62YPG has outstanding recalls

⌵ [Show](#)

---

---

[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)  
[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#).

**OGI**

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)