

Check MOT history

This is a new service – [Complete a quick survey](https://www.smartsurvey.co.uk/s/GIZZX?vrm=SA14CAB&make_result=SKODA&model_result=SUPERB&mot_first_used_date=2014-05-27&vehicle_age=3621&mot_expiry_date=2024-05-19&mot_expiry_date_days_left=24&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) (https://www.smartsurvey.co.uk/s/GIZZX?vrm=SA14CAB&make_result=SKODA&model_result=SUPERB&mot_first_used_date=2014-05-27&vehicle_age=3621&mot_expiry_date=2024-05-19&mot_expiry_date_days_left=24&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) to help us improve.

[< Back](#)

This vehicle's MOT expires soon

SAI4 CAB

SKODA SUPERB

[Check another vehicle \(/\)](#)

Colour
Silver

Fuel type
Diesel

Date registered
27 May 2014

MOT valid until
19 May 2024

[Get an MOT reminder](https://www.gov.uk/mot-reminder) (https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates](/enter-document-reference?registration=SA14CAB) (/enter-document-reference?registration=SA14CAB)

If you think the MOT expiry date or any of the vehicle details are wrong: [contact DVSA](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).

[Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[Hide](#)

Date tested
15 May 2023

Mileage
247,075 miles

MOT test number
6803 1978 3902

Test location

Expiry date

PASS

▶ [View test location](#)

19 May 2024

Monitor and repair if necessary (advisories):

- **Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**
- **Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**
- **Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**

▶ [What are advisories?](#)

Date tested
11 May 2022

PASS

Mileage
234,909 miles

Test location

▶ [View test location](#)

MOT test number
9474 5057 2476

Expiry date
19 May 2023

Date tested
11 May 2022

FAIL

Mileage
234,909 miles

Test location

▶ [View test location](#)

MOT test number
3891 7773 0470

Repair immediately (major defects):

- **Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**

▶ [What are defects?](#)

Date tested
28 April 2021

PASS

Mileage
218,490 miles

Test location

▶ [View test location](#)

MOT test number
7917 9326 4488

Expiry date
19 May 2022

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested
20 May 2020

PASS

Mileage
199,814 miles

MOT test number
1761 6908 8392

Test location

▶ [View test location](#)

Expiry date
19 May 2021

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Small oil leak**

▶ [What are advisories?](#)

Date tested
20 May 2020

FAIL

Mileage
199,814 miles

MOT test number
7803 0333 8355

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Small oil leak**

▶ [What are defects and advisories?](#)

Date tested
13 May 2019

PASS

Mileage
177,261 miles

MOT test number
3527 8328 4877

Test location

▶ [View test location](#)

Expiry date
19 November 2020

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested
13 May 2019

FAIL

Mileage
177,261 miles

MOT test number
1675 8204 3303

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**
- **Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are defects and advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested
17 May 2018

PASS

Mileage
145,447 miles

MOT test number
4622 4751 9073

Test location

▶ [View test location](#)

Expiry date
19 May 2019

Date tested
10 May 2017

PASS

Mileage
109,321 miles

MOT test number
2934 5797 1249

Test location

▶ [View test location](#)

Expiry date
19 May 2018

Date tested
10 May 2017

FAIL

Mileage
109,320 miles

MOT test number
7926 5789 4236

Test location

▶ [View test location](#)

Reason(s) for failure

- **Offside Side repeater has less than 50% of the light sources illuminating (1.4.A.2c)**
- **Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**

▶ [What are failures?](#)

Date tested
5 May 2016

PASS

Mileage
74,655 miles

Test location

▶ [View test location](#)

MOT test number
7739 3588 8604

Expiry date
19 May 2017

Advisory notice item(s)

- **undertrays fitted**

▶ [What are advisories?](#)

Date tested
4 May 2016

FAIL

Mileage
74,654 miles

Test location

▶ [View test location](#)

MOT test number
9169 2022 5644

Reason(s) for failure

- **Nearside Front Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)**
- **Offside Front Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)**
- **Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**

Advisory notice item(s)

- **Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**
- **Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**
- **undertrays fitted**

▶ [What are failures and advisories?](#)

Date tested
20 May 2015

PASS

Mileage
40,575 miles

Test location

▶ [View test location](#)

MOT test number
4183 4014 5174

Expiry date
19 May 2016

Advisory notice item(s)

- **Offside Rear Tyre worn close to the legal limit (4.1.E.1)**

▶ [What are advisories?](#)

Date tested
20 May 2015

Mileage
40,575 miles

MOT test number
6078 5084 5171

FAIL

Test location

▶ [View test location](#)

Reason(s) for failure

- **Nearside Headlamp aim too high (1.8)**

Advisory notice item(s)

- **Offside Rear Tyre worn close to the legal limit (4.1.E.1)**

▶ [What are failures and advisories?](#)

Check for vehicle recalls

See if SKODA SUPERB SA14CAB has outstanding recalls

▼ [Show](#)

[Cookies](#) [Terms and conditions](#) [Privacy notice](#)

[Accessibility statement](#) [MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#).

OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

© [Crown copyright](#)