

Check MOT history

This is a new service — Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX? vrm=DA17WTF&make_result=SKODA&model_result=OCTAVIA&mot_first_used_date=2017-06-01&vehicle_age=2657&mot_expiry_date=2025-03-

<u>09&mot_expiry_date_days_left=181&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV</u>) to help us improve.

< Back

DAI7 WTF

SKODA OCTAVIA

Check another vehicle (/)

Colour Fuel type Date registered
White Diesel 1 June 2017

MOT valid until

9 March 2025

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-document-reference?registration=DA17WTF)

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes)</u>.

Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

◆ Hide

Date tested

1 March 2024

PASS

Mileage 141,185 miles

Test location

View test location

MOT test number **8948 1085 2977**

Expiry date

9 March 2025



Test location

Expiry date

9 March 2024

View test location

Monitor and repair if necessary (advisories):

- Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- What are advisories?

Date tested 7 March 2023



Mileage 101,411 miles MOT test number 4424 9564 9342

Test location

▶ View test location

Repair immediately (major defects):

- Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Monitor and repair if necessary (advisories):

- Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- What are defects and advisories?

Date tested 5 March 2022

PASS

Mileage 58,542 miles

MOT test number **1393 5839 0580**

Test location

Expiry date

9 March 2023

View test location

Monitor and repair if necessary (advisories):

- Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- ▶ What are advisories?

Date tested Mileage MOT test number

10 March 2021

PASS

19,503 miles

Test location

View test location

8311 9627 8362

Expiry date

9 March 2022

Date tested
3 December 2020

PASS

Mileage 18,336 miles

Test location

View test location

MOT test number **3607 6567 2725**

Expiry date

2 December 2021

Date tested 24 May 2020

PASS

Mileage Unknown

Test location

View test location

MOT test number 4652 4574 2313

Expiry date

30 November 2020

Monitor and repair if necessary (advisories):

- COVID-19 6 MONTH EXTENSION
- What are advisories?

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Check for vehicle recalls

See if SKODA OCTAVIA DA17WTF has outstanding recalls

Show

<u>Cookies Terms and conditions Privacy notice Accessibility statement MOT history API Service status</u>

Built by the **Driver & Vehicle Standards Agency**

OGL

All content is available under the $\underline{\text{Open Government Licence v3.0}},$ except where otherwise stated

© Crown copyright