Cookies on MOT history service

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

Accept additional cookies

Reject additional cookies

View cookies (/cookie-preferences)



Check MOT history

Help us make this service better. Give us your feedback (https://www.smartsurvey.co.uk/s/GIZZX? vrm=EXZ599&make_result=MERCEDES-BENZ&model_result=S-Class&mot_first_used_date=2011-03-01&vehicle_age=5258&mot_expiry_date=2026-07-

29&mot_expiry_date_days_left=371&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

< Back

EXZ 599

MERCEDES-BENZ S-Class

Check another vehicle (/)

Colour Fuel type Date registered
Silver Diesel 1 March 2011

MOT valid until

29 July 2026

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-document-reference?registration=EXZ599)

You can get information corrected on your MOT history (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (such as mileage or vehicle details) if it's wrong.

Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

◆ Hide

Date tested 21 July 2025

PASS

Mileage 106,443 miles

Test location

View test location

MOT test number **3744 0441 4421**

Expiry date 29 July 2026

Date tested 30 July 2024

PASS

Mileage 96,888 miles

Test location

▶ View test location

MOT test number 4468 7403 0987

Expiry date 29 July 2025

Date tested **9 February 2024**

PASS

Mileage 94,050 miles

Test location

View test location

MOT test number **2475 4193 1079**

Expiry date

8 February 2025

Date tested 12 July 2023

PASS

Mileage 87,713 miles

Test location

View test location

MOT test number **5039 6106 6943**

Expiry date 11 July 2024

Date tested 21 April 2023

PASS

Mileage 86,816 miles

Test location

View test location

MOT test number **8968 1087 2852**

Expiry date 2 May 2024

Repair as soon as possible (minor defects):

- Steering lock not functioning (7.3 (a))
- Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Monitor and repair if necessary (advisories):

- Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))
- Suspension component mounting prescribed area is corroded but not considered excessive both rear (5.3.6 (a) (i))
- Wheel bearing has slight play both front (5.1.3 (a) (i))
- various components corroding.

- Offside Rear Tyre worn close to legal limit/worn on edge on limit 1.6mm (5.2.3 (e))
- ▶ What are advisories?

Date tested 3 May 2022

PASS

Mileage MOT test number **85,097 miles 7920 6662 1856**

Test location Expiry date 2 May 2023

View test location

Repair as soon as possible (minor defects):

- Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Offside Front Lower Window damaged but not adversely affecting driver's view (3.2 (a) (i))

Monitor and repair if necessary (advisories):

- Front Brake disc worn, pitted or scored, but not seriously weakened both inner faces (1.1.14 (a) (ii))
- Rear Brake disc worn, pitted or scored, but not seriously weakened both inner faces (1.1.14 (a) (ii))
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- What are advisories?

Date tested 29 April 2022



Mileage 85,088 miles MOT test number 1189 6293 5769

Test location

View test location

Do not drive until repaired (dangerous defects):

 Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Monitor and repair if necessary (advisories):

- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

- Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- What are defects and advisories?

Date tested 16 April 2021

PASS

Mileage MOT test number **74,189 miles 7637 9286 2875**

Test location Expiry date
19 April 2022

View test location

Monitor and repair if necessary (advisories):

- Offside Rear Road wheel fractured at bridge over valve (5.2.2 (a))
- ► What are advisories?

Date tested 7 April 2021



Mileage 74,005 miles

MOT test number **2151 6800 5059**

Test location

View test location

Do not drive until repaired (dangerous defects):

- Offside Rear Road wheel has a welding defect (5.2.2 (a))
- What are defects?

Date tested **20 April 2020**

PASS

Mileage 69,318 miles

MOT test number **2064 4797 7060**

Test location

Expiry date
19 April 2021

View test location

Repair as soon as possible (minor defects):

 Front Windscreen damaged but not adversely affecting driver's view chip X2 (3.2 (a) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))
- What are advisories?

Date tested **20 April 2020**



Mileage 69,318 miles

MOT test number **9565 1623 9868**

Test location

View test location

Repair immediately (major defects):

• Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

Repair as soon as possible (minor defects):

 Front Windscreen damaged but not adversely affecting driver's view chip X2 (3.2 (a) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge 2754019 (5.2.3 (e))
- What are defects and advisories?

Date tested 17 April 2019

PASS

Mileage 62,625 miles

Test location

▶ View test location

MOT test number **8254 4654 8015**

Expiry date

16 October 2020

Repair as soon as possible (minor defects):

- Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- What are defects and advisories?

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018).

7 April 2018

PASS

Mileage 56,772 miles

Test location

View test location

MOT test number

6189 8838 6870

Expiry date 8 April 2019

Date tested 8 April 2017

PASS

Mileage 47,749 miles

Test location

View test location

MOT test number **8746 7096 0669**

Expiry date 8 April 2018

Date tested 1 April 2016

PASS

Mileage 36,745 miles

Test location

View test location

MOT test number **5323 7701 8990**

Expiry date 8 April 2017

Date tested 9 April 2015

PASS

Mileage 26,922 miles

Test location

View test location

MOT test number **2361 8949 5041**

Expiry date 8 April 2016

Date tested 23 April 2014

PASS

Mileage 20,628 miles

Test location

View test location

MOT test number **7368 3361 4111**

Expiry date 22 April 2015

Check for vehicle recalls

See if MERCEDES-BENZ S-Class EXZ599 has outstanding recalls





<u>Cookies Terms and conditions Privacy notice Accessibility statement MOT history API Service status</u>

Built by the <u>Driver & Vehicle Standards Agency</u>

OGL

All content is available under the <u>Open Government</u> <u>Licence v3.0</u>, except where otherwise stated

© Crown copyright