

Check MOT history

Help us make this service better. Give us your [feedback \(https://www.smartsurvey.co.uk/s/GIZZX?vrn=MX15JHV&make_result=VAUXHALL&model_result=ZAFIRA&mot_first_used_date=2015-04-28&vehicle_age=3753&mot_expiry_date=2026-08-05&mot_expiry_date_days_left=364&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrn=MX15JHV&make_result=VAUXHALL&model_result=ZAFIRA&mot_first_used_date=2015-04-28&vehicle_age=3753&mot_expiry_date=2026-08-05&mot_expiry_date_days_left=364&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[< Back](#)

MX15 JHV VAUXHALL ZAFIRA

[Check another vehicle \(/\)](#)

Colour
Red

Fuel type
Diesel

Date registered
28 April 2015

MOT valid until
5 August 2026

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-document-reference?registration=MX15JHV\)](/enter-document-reference?registration=MX15JHV)

You can [get information corrected on your MOT history \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (such as mileage or vehicle details) if it's wrong.

[Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[Hide](#)

Date tested
6 August 2025

PASS

Mileage
198,663 miles

Test location

[View test location](#)

MOT test number
3415 6819 7767

Expiry date
5 August 2026

Repair as soon as possible (minor defects):

- **Offside Obligatory mirror slightly damaged (3.3 (b) (i))**
- **Windscreen wiper blade defective (3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Front Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Front ABS wires slightly insecure**
- **Tyre pressure warning on dash**

► [What are advisories?](#)

Date tested
16 May 2024

PASS

Mileage
190,974 miles

Test location

► [View test location](#)

MOT test number
7809 6817 5805

Expiry date
15 May 2025

Repair as soon as possible (minor defects):

- **Front Anti-roll bar ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Oil leak**

► [What are advisories?](#)

Date tested
15 May 2023

PASS

Mileage
178,102 miles

Test location

► [View test location](#)

MOT test number
2994 3029 5816

Expiry date
14 May 2024

Monitor and repair if necessary (advisories):

- **Front Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Rear Nail in tyre**
- **engine oil leak**

► [What are advisories?](#)

Date tested
28 April 2023

Mileage
176,753 miles

MOT test number
5811 5725 8026

FAIL

Test location

► [View test location](#)

Repair immediately (major defects):

- **Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**
- **Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**

Monitor and repair if necessary (advisories):

- **Front Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Rear Nail in tyre**
- **engine oil leak**

► [What are defects and advisories?](#)

Date tested
10 May 2022

PASS

Mileage
138,815 miles

Test location

► [View test location](#)

MOT test number
3876 1560 1795

Expiry date
11 May 2023

Date tested
3 May 2022

FAIL

Mileage
137,899 miles

Test location

► [View test location](#)

MOT test number
6757 7293 4482

Repair immediately (major defects):

- **Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**

► [What are defects and advisories?](#)

Date tested
12 May 2021

PASS

Mileage
95,223 miles

Test location

► [View test location](#)

MOT test number
6180 8155 9344

Expiry date
11 May 2022

Monitor and repair if necessary (advisories):

- **Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement Top mount (5.3.4 (a) (i))**

► [What are advisories?](#)

Date tested
28 April 2020

PASS

Mileage
77,042 miles

Test location

► [View test location](#)

MOT test number
8288 1044 8849

Expiry date
27 April 2021

Date tested
29 June 2019

PASS

Mileage
48,649 miles

Test location

► [View test location](#)

MOT test number
9015 4994 1974

Expiry date
28 June 2020

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Check for vehicle recalls

See if VAUXHALL ZAFIRA MX15JHV has outstanding recalls

⌵ [Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)
[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OG

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)