

Check MOT history

Help us make this service better. Give us your [feedback](https://www.smartsurvey.co.uk/s/GIZZX?vrn=WA64VDN&make_result=FORD&model_result=GALAXY&mot_first_used_date=2014-09-01&vehicle_age=3992&mot_expiry_date=2026-07-22&mot_expiry_date_days_left=350&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) (https://www.smartsurvey.co.uk/s/GIZZX?vrn=WA64VDN&make_result=FORD&model_result=GALAXY&mot_first_used_date=2014-09-01&vehicle_age=3992&mot_expiry_date=2026-07-22&mot_expiry_date_days_left=350&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[Back](#)

WA64 VDN FORD GALAXY

[Check another vehicle \(/\)](#)

Colour
Grey

Fuel type
Diesel

Date registered
1 September 2014

MOT valid until
22 July 2026

[Get an MOT reminder](https://www.gov.uk/mot-reminder) (<https://www.gov.uk/mot-reminder>) by email or text.

[Download test certificates](/enter-document-reference?registration=WA64VDN) (</enter-document-reference?registration=WA64VDN>)

You can [get information corrected on your MOT history](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (<https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes>) (such as mileage or vehicle details) if it's wrong.

[Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[Hide](#)

Date tested
10 July 2025

PASS

Mileage
376,848 miles

Test location

[View test location](#)

MOT test number
3807 2472 3666

Expiry date
22 July 2026

Monitor and repair if necessary (advisories):

- **Play in steering rack inner joint(s) both**
- **Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**

- Rear Direction indicator slightly discoloured both (4.4.3 (a))
- Front Tyre worn close to legal limit/worn on edge both worn on inside edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arm bush(s) (5.3.4 (a) (i))
- Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b))

► [What are advisories?](#)

Date tested
2 July 2025

FAIL

Mileage
375,875 miles

MOT test number
3931 8129 8899

Test location

► [View test location](#)

Repair immediately (major defects):

- Offside Front Position lamp not working (4.2.1 (a) (ii))
- Nearside Rear Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Repair as soon as possible (minor defects):

- Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Monitor and repair if necessary (advisories):

- Play in steering rack inner joint(s) both
- Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Rear Direction indicator slightly discoloured both (4.4.3 (a))
- Front Tyre worn close to legal limit/worn on edge both worn on inside edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Offside Rear Lower Suspension arm damaged but not seriously weakened (5.3.3 (b) (i))
- Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arm bush(s) (5.3.4 (a) (i))
- Brake pedal wearing smooth (1.1.2 (c))
- Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b))

► [What are defects and advisories?](#)

Date tested
23 July 2024

PASS

Mileage
347,465 miles

Test location

► [View test location](#)

MOT test number
7902 2321 2620

Expiry date
22 July 2025

Monitor and repair if necessary (advisories):

- **Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))**
- **Play in steering rack inner joint(s) both ends**
- **Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**

► [What are advisories?](#)

Date tested
22 July 2024

FAIL

Mileage
347,451 miles

Test location

► [View test location](#)

MOT test number
8860 7922 0055

Repair immediately (major defects):

- **Rear Exhaust system insecure bracket broken off (6.1.2 (a))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))**
- **Play in steering rack inner joint(s) both ends**
- **Rear Exhaust heat shield Insecure and resting on silencer**
- **Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**

► [What are defects and advisories?](#)

Date tested
9 August 2023

PASS

Mileage
324,339 miles

Test location

► [View test location](#)

MOT test number
5648 0297 3789

Expiry date
1 September 2024

Repair as soon as possible (minor defects):

- **Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**

Monitor and repair if necessary (advisories):

- **Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**
- **Offside Play in steering rack inner joint(s)**
- **Rear heatshield Insecure, resting on silencer**
- **Offside Rear Lower Suspension arm damaged but not seriously weakened radius arm bent (5.3.3 (b) (i))**
- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

► [What are advisories?](#)

Date tested
2 August 2023

Mileage
323,924 miles

MOT test number
6625 4628 0395

FAIL

Test location

► [View test location](#)

Repair immediately (major defects):

- **Nearside Front Position lamp not working (4.2.1 (a) (ii))**
- **Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**
- **Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**

Repair as soon as possible (minor defects):

- **Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**
- **Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**

Monitor and repair if necessary (advisories):

- **Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**
- **Offside Play in steering rack inner joint(s)**
- **Rear heatshield Insecure, resting on silencer**
- **Offside Rear Lower Suspension arm damaged but not seriously weakened radius arm bent (5.3.3 (b) (i))**
- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

► [What are defects and advisories?](#)

Date tested
8 August 2022

Mileage
297,254 miles

MOT test number
5274 7548 8857

Test location

Expiry date

PASS

► [View test location](#)

1 September 2023

Repair as soon as possible (minor defects):

- **Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Offside Play in steering rack inner joint(s)**
- **Rear Exhaust heat shield insecure**
- **Nearside Front Tyre worn close to legal limit/worn on edge On legal limit 1.6mm (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge on legal limit 1.6mm (5.2.3 (e))**

► [What are advisories?](#)

Date tested
8 August 2022

Mileage
297,254 miles

MOT test number
4764 3534 5876

FAIL

Test location

► [View test location](#)

Repair immediately (major defects):

- **Nearside Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**
- **Offside Position lamp not working (4.2.1 (a) (ii))**

Repair as soon as possible (minor defects):

- **Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Offside Play in steering rack inner joint(s)**
- **Rear Exhaust heat shield insecure**
- **Nearside Front Tyre worn close to legal limit/worn on edge On legal limit 1.6mm (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge on legal limit 1.6mm (5.2.3 (e))**

► [What are defects and advisories?](#)

Date tested
17 August 2021

Mileage
271,963 miles

MOT test number
2493 9691 9972

PASS

Test location

► [View test location](#)

Expiry date
1 September 2022

Repair as soon as possible (minor defects):

- **Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**
- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

► [What are advisories?](#)

Date tested
5 August 2021

Mileage
270,846 miles

MOT test number
8229 0753 7656

FAIL

Test location

► [View test location](#)

Repair immediately (major defects):

- **Reversing lamp inoperative (4.6.1 (a))**
- **Offside Front Position lamp not working (4.2.1 (a) (ii))**
- **Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**

Repair as soon as possible (minor defects):

- **Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**

► [What are defects and advisories?](#)

Date tested
7 August 2020

Mileage
254,723 miles

MOT test number
1716 3633 9164

PASS

Test location

► [View test location](#)

Expiry date
1 September 2021

Repair as soon as possible (minor defects):

- **Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**
- **Offside Play in steering rack inner joint(s)**

► [What are advisories?](#)

Date tested
5 August 2020

FAIL

Mileage
254,663 miles

MOT test number
8532 5384 4992

Test location

► [View test location](#)

Do not drive until repaired (dangerous defects):

- **Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Repair immediately (major defects):

- **Nearside Front Position lamp not working (4.2.1 (a) (ii))**

Repair as soon as possible (minor defects):

- **Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**
- **Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**
- **Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**
- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Offside Play in steering rack inner joint(s)**

► [What are defects and advisories?](#)

Date tested
12 August 2019

PASS

Mileage
238,952 miles

MOT test number
2632 6364 6664

Test location

Expiry date
1 September 2020

► [View test location](#)

Repair as soon as possible (minor defects):

- **Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**
- **Offside Front Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))**

Monitor and repair if necessary (advisories):

- **Offside Rear Lower Suspension arm damaged but not seriously weakened short control arm slightly bent (5.3.3 (b) (i))**
- **Offside Play in steering rack inner joint(s)**

Date tested
12 August 2019

FAIL

Mileage
238,952 miles

MOT test number
3116 8245 7913

Test location

► [View test location](#)

Repair immediately (major defects):

- **Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**

Repair as soon as possible (minor defects):

- **Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**
- **Offside Front Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))**

Monitor and repair if necessary (advisories):

- **Offside Rear Lower Suspension arm damaged but not seriously weakened short control arm slightly bent (5.3.3 (b) (i))**
- **Offside Play in steering rack inner joint(s)**

► [What are defects and advisories?](#)

Date tested
15 August 2018

PASS

Mileage
196,208 miles

MOT test number
1908 3900 1236

Test location

► [View test location](#)

Expiry date
1 September 2019

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested
10 August 2017

PASS

Mileage
129,591 miles

MOT test number
9018 9041 5230

Test location

► [View test location](#)

Expiry date
1 September 2018

Date tested
9 August 2017

FAIL

Mileage
129,432 miles

MOT test number
3398 0133 6983

Test location

► [View test location](#)

Reason(s) for failure

- **Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**

► [What are failures?](#)

Date tested
11 August 2016

PASS

Mileage
66,463 miles

MOT test number
7791 0981 7571

Test location

► [View test location](#)

Expiry date
1 September 2017

Advisory notice item(s)

- **Front slight wear on tyre edges**

► [What are advisories?](#)

Date tested
2 September 2015

PASS

Mileage
14,027 miles

MOT test number
9639 4493 5143

Test location

► [View test location](#)

Expiry date
1 September 2016

Check for vehicle recalls

See if FORD GALAXY WA64VDN has outstanding recalls

▼ [Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)

[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OGI

All content is available under the Open Government
Licence v3.0, except where otherwise stated

© Crown copyright