

Check MOT history

Help us make this service better. Give us your [feedback](https://www.smartsurvey.co.uk/s/GIZZX?vrn=WJ13KVX&make_result=SKODA&model_result=OCTAVIA&mot_first_used_date=2013-05-15&vehicle_age=4474&mot_expiry_date=2026-08-31&mot_expiry_date_days_left=382&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) (https://www.smartsurvey.co.uk/s/GIZZX?vrn=WJ13KVX&make_result=SKODA&model_result=OCTAVIA&mot_first_used_date=2013-05-15&vehicle_age=4474&mot_expiry_date=2026-08-31&mot_expiry_date_days_left=382&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[< Back](#)

WJ13 KVX SKODA OCTAVIA

[Check another vehicle \(/\)](#)

Colour
Silver

Fuel type
Diesel

Date registered
15 May 2013

MOT valid until
31 August 2026

[Get an MOT reminder](https://www.gov.uk/mot-reminder) (<https://www.gov.uk/mot-reminder>) by email or text.

[Download test certificates](/enter-document-reference?registration=WJ13KVX) (</enter-document-reference?registration=WJ13KVX>)

You can [get information corrected on your MOT history](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (<https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes>) (such as mileage or vehicle details) if it's wrong.

[Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[Hide](#)

Date tested
14 August 2025

PASS

Mileage
235,725 miles

Test location

[View test location](#)

MOT test number
7533 9407 4613

Expiry date
31 August 2026

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre worn close to legal limit/worn on edge Below 3mm in centre of tyre (5.2.3 (e))**

► [What are advisories?](#)

Date tested
20 August 2024

PASS

Mileage
218,486 miles

Test location

► [View test location](#)

MOT test number
9671 3710 1359

Expiry date
31 August 2025

Monitor and repair if necessary (advisories):

- **Both rear tyres stepped, perishing and near to the limit.**

► [What are advisories?](#)

Date tested
10 August 2023

PASS

Mileage
203,250 miles

Test location

► [View test location](#)

MOT test number
3104 5256 0103

Expiry date
31 August 2024

Date tested
30 August 2022

PASS

Mileage
184,117 miles

Test location

► [View test location](#)

MOT test number
9658 1563 5275

Expiry date
31 August 2023

Date tested
25 August 2021

PASS

Mileage
162,580 miles

Test location

► [View test location](#)

MOT test number
1527 0158 9284

Expiry date
31 August 2022

Monitor and repair if necessary (advisories):

- **Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))**
- **Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**

► [What are advisories?](#)

Date tested
27 August 2020

PASS

Mileage
144,188 miles

Test location

MOT test number
5317 5339 1403

Expiry date
31 August 2021

► [View test location](#)

Repair as soon as possible (minor defects):

- **Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**

► [What are defects and advisories?](#)

Date tested
28 August 2019

PASS

Mileage
127,801 miles

Test location

► [View test location](#)

MOT test number
7906 0255 6767

Expiry date
31 August 2020

Monitor and repair if necessary (advisories):

- **Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**
- **Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**

► [What are advisories?](#)

Date tested
28 August 2019

FAIL

Mileage
127,801 miles

Test location

► [View test location](#)

MOT test number
8049 4874 9748

Repair immediately (major defects):

- **Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**

Monitor and repair if necessary (advisories):

- **Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**
- **Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**

► [What are defects and advisories?](#)

Date tested
13 August 2018

PASS

Mileage
103,659 miles

Test location

MOT test number
7631 9373 8175

Expiry date
31 August 2019

► [View test location](#)

Date tested
13 August 2018

FAIL

Mileage
103,652 miles

Test location

► [View test location](#)

MOT test number
8314 8493 3519

Repair immediately (major defects):

- **Nearside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**

► [What are defects?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested
14 August 2017

PASS

Mileage
81,749 miles

Test location

► [View test location](#)

MOT test number
5352 1784 4559

Expiry date
31 August 2018

Advisory notice item(s)

- **Front brakes release unevenly just under max imbalance**

► [What are advisories?](#)

Date tested
25 August 2016

PASS

Mileage
58,157 miles

Test location

► [View test location](#)

MOT test number
3145 9867 6205

Expiry date
31 August 2017

Date tested
1 September 2015

PASS

Mileage
29,332 miles

Test location

► [View test location](#)

MOT test number
8231 7331 5287

Expiry date
31 August 2016

Check for vehicle recalls

See if SKODA OCTAVIA WJ13KVB has outstanding recalls

[Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)
[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OG

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)