

Cookies on MOT history service

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

[Accept additional cookies](#)

[Reject additional cookies](#)

[View cookies \(/cookie-preferences\)](/cookie-preferences)



Check MOT history

Help us make this service better. Give us your [feedback \(https://www.smartsurvey.co.uk/s/GIZZX?vrn=AP15TZS&make_result=VAUXHALL&model_result=ZAFIRA&mot_first_used_date=2015-08-17&vehicle_age=3739&mot_expiry_date=2026-08-28&mot_expiry_date_days_left=290&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrn=AP15TZS&make_result=VAUXHALL&model_result=ZAFIRA&mot_first_used_date=2015-08-17&vehicle_age=3739&mot_expiry_date=2026-08-28&mot_expiry_date_days_left=290&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[< Back](#)

API5 TZS VAUXHALL ZAFIRA

[Check another vehicle \(/\)](#)

Colour
Brown

Fuel type
Diesel

Date registered
17 August 2015

MOT valid until
28 August 2026

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-document-reference?registration=AP15TZS\)](/enter-document-reference?registration=AP15TZS)

You can [get information corrected on your MOT history \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (such as mileage or vehicle details) if it's wrong.

[⌵ Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[⬆ Hide](#)

Date tested
29 August 2025

PASS

Mileage
196,635 miles

Test location

► [View test location](#)

MOT test number
3324 7187 9471

Expiry date
28 August 2026

Date tested
11 July 2025

FAIL

Mileage
196,634 miles

Test location

► [View test location](#)

MOT test number
9576 3325 5719

Repair immediately (major defects):

- **Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**
- **Headlamp aim unable to be tested (4.1.2 (b))**
- **Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**
- **Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**
- **Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**

Monitor and repair if necessary (advisories):

- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))**
- **Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))**
- **Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**
- **Offside Rear Tyre worn close to legal limit/worn on edge 225/50/17 (5.2.3 (e))**
- **Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**
- **Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**

► [What are defects and advisories?](#)

Date tested
18 July 2024

PASS

Mileage
181,501 miles

Test location

► [View test location](#)

MOT test number
3180 4290 6067

Expiry date
17 July 2025

Monitor and repair if necessary (advisories):

- Front Macpherson strut pin or bush worn but not resulting in excessive movement both top mountings (5.3.4 (a) (i))
- Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- tpms light illuminated

► [What are advisories?](#)

Date tested
18 July 2024

FAIL

Mileage
181,501 miles

MOT test number
6239 8785 6747

Test location

► [View test location](#)

Do not drive until repaired (dangerous defects):

- **Front Tyre tread depth below requirements of 1.6mm both fronts 225/50/17 (5.2.3 (e))**

Repair immediately (major defects):

- **Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**
- **Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**

Monitor and repair if necessary (advisories):

- **Front Macpherson strut pin or bush worn but not resulting in excessive movement both top mountings (5.3.4 (a) (i))**
- **Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **tpms light illuminated**

► [What are defects and advisories?](#)

Date tested
6 July 2023

PASS

Mileage
165,980 miles

MOT test number
9334 4842 3457

Test location

Expiry date
15 July 2024

► [View test location](#)

Monitor and repair if necessary (advisories):

- **Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**

► [What are advisories?](#)

Date tested
30 June 2023

FAIL

Mileage
165,980 miles

MOT test number
1345 7027 7675

Test location

► [View test location](#)

Repair immediately (major defects):

- **Offside Stop lamp(s) not working (4.3.1 (a) (ii))**
- **Nearside Rear Position lamp not working (4.2.1 (a) (ii))**
- **Offside Rear Fuel hose leaking (6.1.3 (b) (i))**
- **Offside Rear Hydraulic brake cylinder leaking hydraulic fluid (1.1.16 (b) (i))**
- **Parking brake efficiency below requirements (1.4.2 (a) (i))**

Repair as soon as possible (minor defects):

- **Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**

► [What are defects and advisories?](#)

Date tested
15 July 2022

PASS

Mileage
148,332 miles

Test location

► [View test location](#)

MOT test number
7214 6462 5786

Expiry date
15 July 2023

Date tested
15 July 2022

FAIL

Mileage
Unknown

Test location

► [View test location](#)

MOT test number
3475 0307 3035

Do not drive until repaired (dangerous defects):

- **Nearside Front Tyre tread depth below requirements of 1.6mm 225-50-17 (5.2.3 (e))**
- **Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Repair immediately (major defects):

- **Offside Rear Service brake excessively binding (1.2.1 (f))**

Monitor and repair if necessary (advisories):

- **Tyre worn close to legal limit/worn on edge Rears wearing on shoulders (5.2.3 (e))**
- **Offside Rear Wheel bearing has slight play UNABLE TO TEST. BRAKE LOCKED (5.1.3 (a) (i))**

► [What are defects and advisories?](#)

Date tested
5 July 2021

Mileage
122,369 miles

MOT test number
3075 9287 0647

PASS

Test location

► [View test location](#)

Expiry date

15 July 2022

Monitor and repair if necessary (advisories):

- **Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

► [What are advisories?](#)

Date tested
16 July 2020

PASS

Mileage
106,210 miles

Test location

► [View test location](#)

MOT test number
4698 0773 5979

Expiry date

15 July 2021

Date tested
5 August 2019

PASS

Mileage
80,673 miles

Test location

► [View test location](#)

MOT test number
8465 1997 6128

Expiry date

16 August 2020

Date tested
19 July 2018

PASS

Mileage
46,064 miles

Test location

► [View test location](#)

MOT test number
7688 2661 6969

Expiry date

16 August 2019

Monitor and repair if necessary (advisories):

- **Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**

► [What are advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Check for vehicle recalls

See if VAUXHALL ZAFIRA AP15TZS has outstanding recalls

[↕ Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)

[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)