Cookies on Check the MOT history of a vehicle service

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

Accept additional cookies

Reject additional cookies

View cookies (/cookie-preferences)



Check the MOT history of a vehicle

Help us make this service better. Give us your feedback

(https://dvsa.qualtrics.com/jfe/form/SV_7X2O0cNscPctIP4?

vrm=DY63VKL&make_result=VOLKSWAGEN&model_result=PASSAT&mot_first_used_date=2013-09-

30&vehicle_age=4426&mot_expiry_date=2025-11-

14&mot_expiry_date_days_left=2&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

< Back

This vehicle's MOT expires soon

DY63 VKL

VOLKSWAGEN PASSAT

Check another vehicle (/)

Colour Fuel type

Black Diesel

Date registered

30 September 2013

MOT valid until

14 November 2025

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-document-reference?registration=DY63VKL)

You can get information corrected on your MOT history (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (such as mileage or vehicle details) if it's wrong.

Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

♠ Hide

Date tested **29 October 2024**

PASS

Mileage 294,791 miles

94,791 miles 7164 8878 7345

Test location

Expiry date

14 November 2025

MOT test number

View test location

Monitor and repair if necessary (advisories):

- Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Oil leak, but not excessive (8.4.1 (a) (i))
- Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- What are advisories?

Date tested 29 October 2024

FAIL

Mileage 294,791 miles

MOT test number **8572 0136 5289**

Test location

View test location

Repair immediately (major defects):

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Monitor and repair if necessary (advisories):

- Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Oil leak, but not excessive (8.4.1 (a) (i))
- Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- What are defects and advisories?

Date tested Mileage MOT test number

21 October 2023

PASS

260,179 miles

Test location

Expiry date

14 November 2024

7060 5030 2719

View test location

Monitor and repair if necessary (advisories):

- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush splitting. (5.3.4 (a) (i))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush splitting. (5.3.4 (a) (i))
- ► What are advisories?

Date tested 31 October 2022

PASS

Mileage 226,877 miles

Test location

View test location

MOT test number **5773 8075 1670**

Expiry date

14 November 2023

Monitor and repair if necessary (advisories):

- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- What are advisories?

Date tested 31 October 2022



Mileage 226,877 miles

MOT test number

5861 5913 0284

Test location

View test location

Repair immediately (major defects):

 Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Monitor and repair if necessary (advisories):

- Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- What are defects and advisories?

Date tested
4 November 2021

PASS

Mileage

197,548 miles

MOT test number **4457 8885 9631**

Test location

Expiry date

14 November 2022

View test location

Monitor and repair if necessary (advisories):

- Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- What are advisories?

Date tested **10 November 2020**

PASS

Mileage 164,664 miles

Test location

View test location

MOT test number **5811 3623 4508**

Expiry date

14 November 2021

Monitor and repair if necessary (advisories):

- Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- What are advisories?

Date tested **5 November 2019**

PASS

Mileage

134,697 miles

Test location

View test location

MOT test number

8513 8625 0145

Expiry date

14 November 2020

Monitor and repair if necessary (advisories):

- Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- What are advisories?



Mileage 134,677 miles MOT test number 2592 2221 6159

Test location

View test location

Do not drive until repaired (dangerous defects):

 Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Monitor and repair if necessary (advisories):

- Offside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))
- Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- What are defects and advisories?

Date tested **15 November 2018**

PASS

Mileage 90,357 miles

Test location

View test location

MOT test number 1241 1821 1065

Expiry date

14 November 2019

Monitor and repair if necessary (advisories):

- Under trays fitted
- What are advisories?

Date tested 12 July 2018

PASS

Mileage 80,390 miles

Test location

View test location

MOT test number

9289 9099 8627

Expiry date 25 July 2019

MOT test number

2920 9723 2909

Date tested 12 July 2018



Mileage

80,389 miles

Test location

View test location

Repair immediately (major defects):

- Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested 6 July 2017

PASS

Mileage 51,928 miles

MOT test number **1890 2472 6856**

Test location

Expiry date 25 July 2018

View test location

Advisory notice item(s)

- Offside Front Outer Brake pad(s) wearing thin (3.5.1g)
- Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Offside Front Tyre worn close to the legal limit (4.1.E.1)
- · both rear tyres begginning to wear on inner edges
- What are advisories?

Date tested 26 July 2016

PASS

Mileage 31,633 miles

MOT test number **3085 2684 2589**

Test location

Expiry date **25 July 2017**

▶ View test location

VIOW LOCK ICCURION

Advisory notice item(s)

- osf fog lamp / day time running lamp out
- ▶ What are advisories?

Check for vehicle recalls

See if VOLKSWAGEN PASSAT DY63VKL has outstanding recalls





<u>Cookies Terms and conditions Privacy notice</u>

<u>Accessibility statement MOT history API Service status</u>

Built by the <u>Driver & Vehicle Standards Agency</u>

OGL

All content is available under the <u>Open Government</u> <u>Licence v3.0</u>, except where otherwise stated

© Crown copyright