

Cookies on Check the MOT history of a vehicle service

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

[Accept additional cookies](#)

[Reject additional cookies](#)

[View cookies \(/cookie-preferences\)](#)



Check the MOT history of a vehicle

Help us make this service better. Give us your [feedback](#)
(https://dvsa.qualtrics.com/jfe/form/SV_7X200cNscPctIP4?)

https://dvsa.gov.uk/mot-history/7X200cNscPctIP4?vrm=KN64THV&make_result=SEAT&model_result=ALHAMBRA&mot_first_used_date=2014-09-30&vehicle_age=4151&mot_expiry_date=2026-10-14&mot_expiry_date_days_left=246&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=GV).

[< Back](#)

KN64 THV

SEAT ALHAMBRA

[Check another vehicle \(/\)](#)

Colour

Black

Fuel type

Diesel

Date registered

30 September 2014

MOT valid until

14 October 2026

[Get an MOT reminder](#) (<https://www.gov.uk/mot-reminder>) by email or text.

[Download test certificates](#) (</enter-document-reference?registration=KN64THV>)

You can [get information corrected on your MOT history](#) (<https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes>) (such as mileage or vehicle details) if it's wrong.

[Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

 Hide

Date tested
15 October 2025

Mileage
247,947 miles

MOT test number
8569 1538 9417

PASS

Test location

Expiry date
14 October 2026

► [View test location](#)

Monitor and repair if necessary (advisories):

- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- [What are advisories?](#)

Date tested
28 September 2024

Mileage
239,074 miles

MOT test number
6297 1559 8642

PASS

Test location

Expiry date
13 October 2025

► [View test location](#)

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**
- **Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge 1.6mm inner edge (5.2.3 (e))**

► [What are advisories?](#)

Date tested
14 October 2023

Mileage
220,074 miles

MOT test number
4450 5399 4344

PASS

Test location

Expiry date
13 October 2024

► [View test location](#)

Date tested
29 September 2022

Mileage
214,505 miles

MOT test number
2431 9198 8074

PASS

Test location

Expiry date

► [View test location](#)

13 October 2023

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

► [What are advisories?](#)

Date tested
29 September 2022

Mileage
214,505 miles

MOT test number
4622 7451 3594

FAIL

Test location

► [View test location](#)

Repair immediately (major defects):

- **Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

► [What are defects and advisories?](#)

Date tested
30 September 2021

Mileage
189,139 miles

MOT test number
2968 7738 8697

PASS

Test location

Expiry date
13 October 2022

► [View test location](#)

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Rear Brake lining(s) wearing thin (1.1.13 (a) (ii))**
- **rear tyres wearing on inner edge**

► [What are advisories?](#)

Date tested
25 September 2020

Mileage
167,899 miles

MOT test number
3401 6494 5831

PASS

Test location
► [View test location](#)

Expiry date
13 October 2021

Monitor and repair if necessary (advisories):

- **n/s rear light lens damaged**
- **n/s o/s front tyre treads worn on inner edges**
- **Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**
- **Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**

► [What are advisories?](#)

Date tested
24 September 2020

Mileage
167,793 miles

MOT test number
3135 0987 8916

FAIL

Test location
► [View test location](#)

Do not drive until repaired (dangerous defects):

- **Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Monitor and repair if necessary (advisories):

- **n/s rear light lens damaged**
- **n/s o/s front tyre treads worn on inner edges**
- **Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**
- **Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**

► [What are defects and advisories?](#)

Date tested
25 September 2019

Mileage
147,655 miles

MOT test number
4486 2366 3844

PASS

Test location
► [View test location](#)

Expiry date
13 October 2020

Monitor and repair if necessary (advisories):

- **Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**
- **Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**

► [What are advisories?](#)

Date tested
25 September 2019

Mileage
147,655 miles

MOT test number
5513 5191 9201

FAIL

Test location

► [View test location](#)

Do not drive until repaired (dangerous defects):

- **Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Repair immediately (major defects):

- **Offside Suspension arm pin or bush excessively worn front arm (rear bush) (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**
- **Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**

► [What are defects and advisories?](#)

Date tested
4 October 2018

Mileage
117,717 miles

MOT test number
4111 5348 8548

PASS

Test location

Expiry date
13 October 2019

► [View test location](#)

Monitor and repair if necessary (advisories):

- **Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**
- **Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **n/s o/s front tyre treads 3mm**
- **Front Suspension arm pin or bush worn but not resulting in excessive movement n/s o/s (5.3.4 (a) (i))**

► [What are advisories?](#)

Date tested
4 October 2018

Mileage
117,717 miles

MOT test number
8230 7629 9077

FAIL

Test location

► [View test location](#)

Do not drive until repaired (dangerous defects):

- **Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**

Monitor and repair if necessary (advisories):

- **Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**

- Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- n/s o/s front tyre treads 3mm
- Front Suspension arm pin or bush worn but not resulting in excessive movement n/s o/s (5.3.4 (a) (i))

► [What are defects and advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\).](https://www.gov.uk/government/news/mot-changes-20-may-2018)

Date tested
14 October 2017

Mileage
75,377 miles

MOT test number
1075 6533 1832

PASS

Test location

Expiry date
13 October 2018

► [View test location](#)

Advisory notice item(s)

- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**

► [What are advisories?](#)

Date tested
13 October 2017

Mileage
75,377 miles

MOT test number
2659 2890 0069

FAIL

Test location

► [View test location](#)

Reason(s) for failure

- **Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**

Advisory notice item(s)

- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**

► [What are failures and advisories?](#)

Check for vehicle recalls

See if SEAT ALHAMBRA KN64THV has outstanding recalls

 [Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)
[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)