

Cookies on Check the MOT history of a vehicle service

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

[Accept additional cookies](#)

[Reject additional cookies](#)

[View cookies \(/cookie-preferences\)](#)



Check the MOT history of a vehicle

Help us make this service better. Give us your [feedback](#)

(https://dvsa.qualtrics.com/jfe/form/SV_7X200cNscPctIP4?vrm=LN68NSU&make_result=MERCEDES-BENZ&model_result=S-Class&mot_first_used_date=2018-09-10&vehicle_age=2710&mot_expiry_date=2027-01-29&mot_expiry_date_days_left=353&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[Back](#)

LN68 NSU

MERCEDES-BENZ S-Class

[Check another vehicle \(/\)](#)

Colour

Blue

Fuel type

Diesel

Date registered

10 September 2018

MOT valid until

29 January 2027

[Get an MOT reminder \(<https://www.gov.uk/mot-reminder>\)](#) by email or text.

[Download test certificates \(/enter-document-reference?registration=LN68NSU\)](#)

You can [get information corrected on your MOT history \(<https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes>\)](#) (such as mileage or vehicle details) if it's wrong.

[Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

 Hide

Date tested
30 January 2026

Mileage
128,023 miles

MOT test number
2246 2112 7515

PASS

Test location
► [View test location](#)

Expiry date
29 January 2027

Date tested
6 January 2025

Mileage
125,429 miles

MOT test number
1384 3043 7494

PASS

Test location
► [View test location](#)

Expiry date
5 January 2026

Date tested
19 September 2024

Mileage
201,929 km

MOT test number
2868 2231 4013

PASS

Test location
► [View test location](#)

Expiry date
18 September 2025

Date tested
26 July 2024

Mileage
124,427 miles

MOT test number
6155 3623 3929

PASS

Test location
► [View test location](#)

Expiry date
25 July 2025

Monitor and repair if necessary (advisories):

- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement both lower arms (5.3.4 (a) (i))**
- **Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))**

► [What are advisories?](#)

Date tested
5 September 2023

Mileage
123,424 miles

MOT test number
6758 3505 5633

PASS

Test location
► [View test location](#)

Expiry date
4 September 2024

Date tested
7 March 2023

PASS

Mileage
106,061 miles

MOT test number
8994 4138 2486

Test location

► [View test location](#)

Expiry date
6 March 2024

Monitor and repair if necessary (advisories):

- **Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))**
- **Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))**

► [What are advisories?](#)

Date tested
9 September 2022

PASS

Mileage
90,933 miles

MOT test number
9152 5911 6355

Test location

► [View test location](#)

Expiry date
8 September 2023

Monitor and repair if necessary (advisories):

- **Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**
- **Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))**
- **Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))**

► [What are advisories?](#)

Date tested
14 March 2022

PASS

Mileage
72,757 miles

MOT test number
6575 5094 4324

Test location

► [View test location](#)

Expiry date
13 March 2023

Monitor and repair if necessary (advisories):

- **Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))**
- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**

► [What are advisories?](#)

Date tested

Mileage

MOT test number

10 September 2021

PASS

52,487 miles

2436 0607 3924

Test location

Expiry date

9 September 2022

► [View test location](#)

Monitor and repair if necessary (advisories):

- **Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))**
- **Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))**
- **Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**

► [What are advisories?](#)

Date tested
7 April 2021

PASS

Mileage
39,995 miles

MOT test number
2388 3026 6422

Test location

Expiry date
6 April 2022

► [View test location](#)

Monitor and repair if necessary (advisories):

- **Offside Rear Nail in tyre**
- **Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))**
- **Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))**

► [What are advisories?](#)

Date tested
10 September 2020

PASS

Mileage
39,473 miles

MOT test number
9522 3917 6770

Test location

Expiry date
9 September 2021

► [View test location](#)

Date tested
5 March 2020

PASS

Mileage
38,917 miles

MOT test number
5622 9680 3856

Test location

Expiry date
4 March 2021

► [View test location](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Check for vehicle recalls

See if MERCEDES-BENZ S-Class LN68NSU has outstanding recalls

 [Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)
[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

[© Crown copyright](#)