



Check MOT history (<https://www.gov.uk/check-mot-history>).

SP58YVM

## SKODA OCTAVIA

Colour  
**Silver**

Fuel type  
**Diesel**

Date registered  
**24 December 2008**

MOT valid until  
**7 September 2020**

### MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested  
**6 September 2019**

**PASS**

Mileage  
**291,131 miles**

Test location

MOT test number  
**7313 1960 0163**

Expiry date  
**7 September 2020**

Monitor and repair if necessary (advisories):

- Oil leak, but not excessive (8.4.1 (a) (i))

Date tested  
**31 August 2018**

**PASS**

Mileage  
**253,476 miles**

Test location

MOT test number  
**1360 5934 9963**

Expiry date  
**7 September 2019**

Monitor and repair if necessary (advisories):

- under tray fitted
- Front Both front wishbones rear bushes perished

Date tested  
**28 August 2018**

**FAIL**

Mileage  
**253,169 miles**

Test location

MOT test number  
**6268 2441 3723**

Repair immediately (major defects):

- **Nearside Side repeater not working (4.4.1 (a) (ii))**
- **Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**

Repair as soon as possible (minor defects):

- **Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **under tray fitted**
- **Front Both front wishbones rear bushes perished**

---

### The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

---

Date tested  
**31 August 2017**

**PASS**

Mileage  
**215,329 miles**

Test location

MOT test number  
**2927 2986 0759**

Expiry date  
**7 September 2018**

Advisory notice item(s)

- **Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**
- **Nearside Front Wishbone rear bush slightly perished**
- **Offside Front Wishbone rear bush slightly perished**
- **Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**
- **Both front tyres wearing on inner edge**

---

Date tested  
**8 September 2016**

**PASS**

Mileage  
**172,291 miles**

Test location

MOT test number  
**3581 6722 4240**

Expiry date  
**7 September 2017**

---

Date tested  
**5 September 2016**

**FAIL**

Mileage  
**172,180 miles**

Test location

MOT test number  
**6222 4226 8303**

Reason(s) for failure

- **Nearside Headlamp aim too high (1.8)**
- **Offside Headlamp aim too high (1.8)**

- Exhaust emits an excessive level of metered smoke  
2.03 (7.4.B.3a)

Date tested  
18 January 2016

**PASS**

Mileage  
146,668 miles

Test location

MOT test number  
8176 4071 0307

Expiry date  
9 February 2017

Advisory notice item(s)

- Nearside Front Tyre worn close to the legal limit  
(4.1.E.1)

Date tested  
18 January 2016

**FAIL**

Mileage  
146,668 miles

Test location

MOT test number  
2246 0978 2855

Reason(s) for failure

- Nearside Headlamp aim too high (1.8)
- Offside Headlamp aim too high (1.8)

Advisory notice item(s)

- Nearside Front Tyre worn close to the legal limit  
(4.1.E.1)

Date tested  
5 February 2015

**PASS**

Mileage  
119,786 miles

Test location

MOT test number  
1060 2613 5064

Expiry date  
9 February 2016

Advisory notice item(s)

- Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)
- Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)
- front tyre treads starting to perish.

Date tested  
5 February 2015

**FAIL**

Mileage  
119,786 miles

Test location

MOT test number  
8763 7663 5036

Reason(s) for failure

- Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Nearside Rear Brake cable insecure (3.5.1d)
- Offside Front Shock absorber has a serious fluid leak (2.7.3)

## Advisory notice item(s)

- Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- front tyre treads starting to perish.

Date tested  
10 February 2014

**PASS**

Mileage  
101,865 miles

Test location

MOT test number  
9369 8144 4013

Expiry date  
9 February 2015

## Advisory notice item(s)

- Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Offside Brake pad(s) wearing thin (3.5.1g)
- Under-trays fitted obscuring some underside components
- Engine covers fitted obscuring some components in the engine bay

Date tested  
15 August 2013

**PASS**

Mileage  
92,635 miles

Test location

MOT test number  
3671 2702 3458

Expiry date  
14 August 2014

## Advisory notice item(s)

- Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Spare tyre defective
- Under-trays fitted obscuring some underside components

Date tested  
**13 August 2013**

**FAIL**

Mileage  
**92,629 miles**

MOT test number  
**3488 6582 3225**

Test location

Reason(s) for failure

- **Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**
- **Parking brake: efficiency below requirements (3.7.B.7)**

Advisory notice item(s)

- **Nearside Front Shock absorber has a light misting of oil (2.7.3)**
- **Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Spare tyre defective**
- **Under-trays fitted obscuring some underside components**

Date tested  
**30 January 2013**

**PASS**

Mileage  
**70,398 miles**

MOT test number  
**1082 2083 3061**

Test location

Expiry date  
**6 February 2014**

Date tested  
**29 January 2013**

**FAIL**

Mileage  
**70,311 miles**

MOT test number  
**1072 6972 3087**

Test location

Reason(s) for failure

- **Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**
- **Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**

Advisory notice item(s)

- **body under tray damaged**

Date tested  
**7 February 2012**

**PASS**

Mileage  
**39,984 miles**

MOT test number  
**8374 7823 2088**

Test location

Expiry date  
**6 February 2013**

Advisory notice item(s)

- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**
- **Offside Front Tyre worn close to the legal limit (4.1.E.1)**

---

Date tested  
**1 February 2011**

**PASS**

Mileage  
**26,003 miles**

Test location

MOT test number  
**5980 4283 1042**

Expiry date  
**31 January 2012**

---

Date tested  
**22 January 2010**

**PASS**

Mileage  
**11,025 miles**

Test location

MOT test number  
**9910 5272 0058**

Expiry date  
**21 January 2011**

---

### Outstanding vehicle recalls

Check if SKODA OCTAVIA SP58YVM has outstanding recalls

---