



Check MOT history (<https://www.gov.uk/check-mot-history>)

KV09WPK

MERCEDES E 220

Colour
Silver

Fuel type
Diesel

Date registered
30 March 2009

MOT valid until
26 April 2021

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested
27 April 2020

PASS

Mileage
270,141 miles

Test location

MOT test number
4420 3475 7589

Expiry date
26 April 2021

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**

Date tested
27 April 2020

FAIL

Mileage
270,141 miles

Test location

MOT test number
5431 1841 3310

Repair immediately (major defects):

- **Offside Front Headlamp light intensity severely reduced (4.1.4 (a))**
- **Offside Front Lower Suspension arm ball joint excessively worn spring control arm ball joint (5.3.4)**

(a) (i))

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**
- **Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**
- **Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**

Date tested
24 April 2019**PASS**Mileage
246,021 miles

Test location

MOT test number
6563 7835 1693Expiry date
23 October 2020**The MOT test changed on 20 May 2018**

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
15 May 2018**PASS**Mileage
216,168 miles

Test location

MOT test number
5222 3915 9149Expiry date
10 June 2019Date tested
15 May 2017**PASS**Mileage
179,313 miles

Test location

MOT test number
7519 2056 6625Expiry date
10 June 2018Date tested
15 May 2017**FAIL**Mileage
179,312 miles

Test location

MOT test number
9712 4811 5684

Reason(s) for failure

- **Offside Windscreen washer provides insufficient washer liquid (8.2.3)**
- **rear parking (secondary) brakes imbalanced (3.7.B.6b)**

Date tested
25 May 2016

PASS

Mileage
142,083 miles

Test location

MOT test number
3507 1486 1072

Expiry date
10 June 2017

Advisory notice item(s)

- Front Brake disc's worn.
- Offside Front wheel bearing has slight play (2.5.A.3c)

Date tested
19 May 2016

FAIL

Mileage
141,936 miles

Test location

MOT test number
3667 7533 2886

Reason(s) for failure

- Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Nearside Headlamp incorrect colour pink (1.7.5b)

Advisory notice item(s)

- Front Brake disc's worn.
- Offside Front wheel bearing has slight play (2.5.A.3c)

Date tested
18 May 2015

PASS

Mileage
106,735 miles

Test location

MOT test number
3875 5863 5190

Expiry date
10 June 2016

Advisory notice item(s)

- Items removed from driver's view prior to test

Date tested
22 May 2014

PASS

Mileage
58,703 miles

Test location

MOT test number
3372 9284 4109

Expiry date
10 June 2015

Advisory notice item(s)

- nearside rear tyre down to 2 mm

Date tested
11 June 2013

Mileage
16,354 miles

Test location

MOT test number
6753 8236 3175

Expiry date

PASS**10 June 2014**Date tested
18 May 2012Mileage
13,058 milesMOT test number
7498 5913 2105**PASS**

Test location

Expiry date
17 May 2013

Outstanding vehicle recallsCheck if MERCEDES E 220 KV09WPK has outstanding recalls
