

Check MOT history (https://www.gov.uk/check-mot-history)

EY550UD

VOLKSWAGEN SHARAN

Colour Fuel type Date registered

Black Diesel 1 September 2005

MOT valid until

7 January 2023

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested Mileage MOT test number

13 December 2021 207,575 miles 8023 6545 9943

PASS Test location Expiry date

7 January 2023

Repair as soon as possible (minor defects):

• Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Monitor and repair if necessary (advisories):

- Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Date tested

16 December 2020

PASS

Mileage

200,204 miles

MOT test number

9001 8048 9517

Test location Expiry date

7 January 2022

Date tested

28 June 2019

PASS

Mileage

169,053 miles

MOT test number

6500 1274 2630

Test location Expiry date

7 January 2021

Monitor and repair if necessary (advisories):

• Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

• Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Date tested

28 June 2018

PASS

Mileage

127,446 miles

MOT test number

1060 4352 0676

Test location

Expiry date

7 July 2019

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested 5 July 2017 PASS	Mileage 94,571 miles Test location	MOT test number 7976 7775 8274 Expiry date
		7 July 2018
Date tested 6 July 2016	Mileage 81,974 miles	MOT test number 4962 9545 3816
PASS	Test location	Expiry date 7 July 2017
Date tested 3 July 2015	Mileage 72,496 miles	MOT test number 7472 1478 5117
PASS	Test location	Expiry date 7 July 2016
Date tested 8 July 2014	Mileage 61,555 miles	MOT test number 2398 4928 4108
PASS	Test location	Expiry date 7 July 2015

Advisory notice item(s)

- Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Offside Front Tyre worn close to the legal limit (4.1.E.1)

• Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

7 July 2014

FAIL

Mileage

MOT test number

61,555 miles

5759 2898 4135

Test location

Reason(s) for failure

Rear Exhaust has a major leak of exhaust gases (7.1.2)

Advisory notice item(s)

- Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Date tested

PASS

26 June 2013

Mileage

MOT test number

51,452 miles

9570 5777 3165

Test location

Expiry date

7 July 2014

Date tested

6 July 2012

PASS

Mileage

42,761 miles

MOT test number

3367 1818 2148

Test location

Expiry date

7 July 2013

Advisory notice item(s)

	 nearside rear tyre cracking on outer sidewall Spare tyre defective 		
Date tested	Mileage	MOT test number	
8 July 2011	37,867 miles	3780 0948 1154	
PASS	Test location	Expiry date	
		7 July 2012	
Date tested	Mileage	MOT test number	
7 July 2010	33,609 miles	9802 3888 0121	
PASS	Test location	Expiry date	
		7 July 2011	
	Advisory notice item(s) • Nearside Front Tyre worn close to the legal limit (4.1.E.1) • Offside Front Tyre worn close to the legal limit (4.1.E.1)		
Date tested	Mileage	MOT test number	
7 July 2009	29,587 miles	9537 9828 9154	
PASS	Test location	Expiry date	
		7 July 2010	
Date tested	Mileage	MOT test number	
8 July 2008	22,761 miles	2704 4099 8168	
_	22,701 Hilles	2704 4033 6166	

• Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

7 July 2009

Outstanding vehicle recalls

Check if VOLKSWAGEN SHARAN EY55OUD has outstanding recalls